

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-31707
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-155
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	78
9. Pool Name or Wildcat	VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL ☐ GAS WELL ☐ OTHER Water Injection
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>E</u> : <u>2491</u> Feet From The <u>North</u> Line and <u>127</u> Feet From The <u>West</u> Line Section <u>36</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>Lea</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ Squeeze Lower Paddock/Add Perfs

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-30-99: MIRU. NUBOP. REL PKR. TIH W/BIT, PICKING UP 99 JTS 2 7/8" TBG.
8-31-99: TAG @ 6042'. RU REV EQPT. DRILL OUT HARD SCALE 6042-6200'. TIH W/CMT RET & TBG TO 5914'.
9-01-99: PUMP THRU RET W/20 BBLs. SET RET @ 5914'. TEST TBG TO 3000 PSI. PSI CSG TO 500. OK. CMT SQZ PERFS W/100 SX CL C W/.4%
D-156 FLUID LOSS, .2% D-46 ANTI FOAM AGENT, .3% D-65 DISPERSANT. FLSH W/25 1/2 BBLs. SQZ TO 2900 PSI. REV OUT 30 SX CMT.
9-02-99: TIH W/BIT, DC'S & TBG. TAG @ 5913'. DRILL CMT 5913-15. DRILL CMT RET 5915-17. DRILL CMT 5917-6020. CIRC CLN. TEST TO 300 PSI.
OK.
9-03-99: TIH W/PERF GUN. PERF IN GLORIETA FORM FR 5796-5810, 5816-26, 5922-49, 5988-91. TIH W/PKR, SN ON TBG. PSA 5740'. RU PUMP
TRUCK. TEST BACKSIDE TO 500#-OK.
9-07-99: PRESS CSG TO 500#-OK. ACIDIZE GLORIETA PERFS FR 5796-5991' W/3500 GALS 15% NEFE HCL W/1250# RK SLT. PUMP IN 3 STGS.
REL PKR. TIH TO CLEAR PERFS. TAG SALT FILL @ 6000-OK.
9-09-99: TIH W/PKR W/ON-OFF TOOL, CMT LINED TBG TO 5743'. LOAD TBG & ATTEMPT TO SET PKR. WOULD SET IN COMPRESSION, NOT
TENSION.
9-10-99: TIH W/PKR, ON/OFF TOOL, NIPPLE, TBG, SET @ 14' KB @ 5742'. PERFS 5796-5991'. NDBOP. NUWH. TEST CSG TO 500 PSI-OK. CHART
FOR NMOCD. INSTL WIW LINE. WELL RETURNED TO WIW. RIG DOWN.
9-14-99: ON 24 HR OPT. INJ'G 623 BWPD @ 1750 PSI.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 09/16/1999
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED BY [Signature] TITLE Representative DATE SEP 28 1999
CONDITIONS OF APPROVAL, IF ANY:

5C 5

1

