

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-31838
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-1056-2
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	41
9. Pool Name or Wildcat	VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3995' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL ☐ GAS WELL ☐ OTHER INJECTION ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>J</u> : <u>1377</u> Feet From The <u>SOUTH</u> Line and <u>1646</u> Feet From The <u>EAST</u> Line Section <u>25</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	perf/acidize upper glorieta ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-26-00: MIRU. PUMP 40 BBLS 10# BRINE DN TBG. NDWH. NUBOP. REL PKR. TIH W/BIT, DC'S & TBG. STOP BIT @ 1500'.
 5-30-00: PU WS. TAG FILL @ 6099'. BREAK CIRC. C/O TO PBTD @ 6300'. TIH W/PKR, SN & TBG TO 1600'.
 5-31-00: PSA 5902'. TEST CSG/PKR TO 500 PSI-OK. REL PKR. TIH W/CMT RET TO 5902'. PUMP THRU & SET RET @ 5902'. TEST TBG TO 2000 PSI.
 6-01-00: MIX 100 SX CL C & 100 SX CL C NEAT. FLSH W/33 BBLS. TIH W/BIT, DC'S & TBG TO 3355'.
 6-02-00: TAG CMT @ 5900'. DRILL 2' CMT. DRILL CMT RET 5902-04. DRILL HARD CMT 5904-6000. DISPL CSG W/2% KCL.
 6-05-00: PERF CSG IN GLORIETA 5830-62, 5900-5910, 5922-5950, 5956-70, 5978-090. TIH W/PKR, SN & TBG TO 3100'.
 6-06-00: PSA 5786'. ACIDIZE GLOR PERFS 5830-5990 W/9000 GALS 15% NEFE & 2000# RK SLT. FLOW WELL TO TANK.
 6-07-00: REL PKR. TIH W/PKR & TAG PBTD @ 5997'. NO FILL.
 6-08-00: TIH W/PUM OUT PLUG, PKR, ON/OFF TOOL, 2 3/8" CMT LINED TBG. PSA 13', KB @ 5788. REL ON/OFF TOOL. NDBOP. NUWH. TEST CHART CSG TO 500 PSI. PUMP DN TBG.
 6-09-00: RIG DOWN.
 6-16-00: ON 24 HR OPT. INJ'G 2910 BWPD @ 924 PSI.
 FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 6/26/00
 TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED _____ TITLE _____ DATE _____
 BY CONDITIONS OF APPROVAL IF ANY _____

