Office	State of New Mexico			. , ••••	Form C-103
District I	Energy, Minerals and Natural Resources				Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-025-31888	CY
District III	1220 South St. Francis Dr.			5. Indicate Type	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			STATE	
1220 S. St. Francis Dr., Santa Fe, NM 87505		,, 1,1,1		6. State Oil & 0 LG-607	Gas Lease No.
	TICES AND REPORTS ON			7. Lease Name o	r Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				REDHAWK "32" STATE	
Type of Well: Oil Well □ Gas Well ☑ Other					
2. Name of Operator				8. Well No.	
ASHER ENTERPRISES LTD CO				1	
3. Address of Operator				9. Pool name or Wildcat	
P.O. BOX 423, ARTESIA, NM 88210				QUAIL RIDGE (MORROW)	
4. Well Location					
Unit Letter L : 1980 feet from the S line and 810 feet from the W line					
Section 32	Township 19	S F	Range 34E	NMPM LI	EA County
	10. Elevation (Show we				out county
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF IN	NTENTION TO:	iicate in		SEQUENT RE	
PERFORM REMEDIAL WORK			REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRII	LING OPNS.	PLUG AND
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	D 🗆	ABANDONMENT
OTHER: RECOMPLETION		<b>Z</b>	OTHER:		
12. Describe proposed or comple	ted operations (Clearly sta	_		ve pertinent detec	including agrimated data
of starting any proposed work	). SEE RULE 1103. For M	Aultiple C	Completions: Attach	wellbore diagram	of proposed completion
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.					
We intend to abandon the Morrow and norf the Done Springs, retained the St. alex and CIDD @ 12, 1002					
We intend to abandon the Morrow and perf the Bone Springs, retrieve the weak pkr, set CIBP @ 13, 100' w/35'cmt on top of plug.					
w 33 cint on top of p	iug.			09:2031-	350
Run correlation log &	nerf 10 148 _ 10 158	, 2 enf	70 holes total as	ant only	- da 70°11
Run correlation log & perf 10,148 – 10, 158', 2 spf, 20 holes total, spot acid & break down. Results will dictate further activity.					
dictate faithful delivity	/ •			9	1011
				i de Maria	700 20
				\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
				Neg	
					10113
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE COLOR	Colhum 1	TITLE	AGENT_	DATE	8/26/02
Type or print name				Teleph	none No.
(This space for State use)	Osk	GINAL S	GNED BY		
APPPROVED BY		STAT M	INK '	هموری در و در در سری در سری	To 4 0000
Conditions of approval, if any:		FIELD RE	PRESENTATIVE II/	STAFF MANAGER	DATE
or approvat, it airy.				OE	P 0 3 2002

ر ا