

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-32003
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-607
7. Lease Name or Unit Agreement Name Redhawk "32" State
8. Well No. 2
9. Pool name or Wildcat Quail Ridge (Morrow)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Mitchell Energy Corporation	
3. Address of Operator Box 4000, The Woodlands, TX 77387	
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 32 Township 19S Range 34E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3661' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OP'NS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Initial completion attempt <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/2/93 MIRU PU. ND temp tree. NU BOP. Ran GR/CBL/CCL tagged to high.
9/5-6/93 RIH w/2 7/8" N-80 tbg & drilled to 13,521'. Displ hole w/2.4 bbls 2% KCl. POOH & LD bit.
9/8/93 RIH w/GR/CBL/CCL & log from 13,508' to 8390'. RIH w/pkr & 2 7/8" tbg.
9/9/93 Set pkr @ 13,006'. ND BOP. NU tree. Swab FL to 9500'. RIH w/pivot gun & perf Morrow "C" 4 SPF from 13,482-92'. RU swab. IFL @ 6300'. Swabbed to 6000'. Slight blow.
9/10/93 12 hr SITP 80 psi. IFL @ 3000'. Made 14 runs - rec 111 BW. FFL @ 11,000'.
9/11/93 14 hr SITP 40 psi. IFL @ 5200'. Made 7 runs - rec 45 BW. FFL @ 12,000'.
9/14/93 64 hr SITP 180 psi. IFL @ 2800'. Swabbed 76 BW. FFL @ 13,000'.
9/15/93 14 hr SITP 40 psi. IFL @ 6500'. Swabbed 48 BW. FFL @ 13,000'.
10/5/93 Load hole w/15 BW. ND tree. NU BOP. POOH w/tbg. RIH & set CIBP @ 13,468'. Dumped 30' cmt on top.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James Blount TITLE Engineer DATE 11/2/93
TYPE OR PRINT NAME James Blount TELEPHONE NO. (915) 682-5396

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE NOV 17 1993

CONDITIONS OF APPROVAL, IF ANY: