

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-32410
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER DRY	7. Lease Name or Unit Agreement Name Shelley 5
2. Name of Operator Matador Operating Company	8. Well No. 1
3. Address of Operator 415 W. Wall, Ste 1101, Midland, TX 79701	9. Pool name or Wildcat Lovington Abo
4. Well Location Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line Section 5 Township 17S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3799' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Dowell Schlumberger plugged as follows:

35 sx Class H 8885'-8780'
35 sx Class H 7881'-7776'
35 sx Class C 6159'-6027'
45 sx Class C 4291'-4121'
35 sx Class C 2168'-2036'
15 sx Class C 30'-surface

Cut off casing and set dry hole marker.
Per orders from Jerry Sexton NMOCD, Hobbs, NM

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry King TITLE Engineering Tech DATE 2-24-94
TYPE OR PRINT NAME JERRY KING TELEPHONE NO. 915-687-5960

(This space for State Use)

APPROVED BY Johnny Robinson TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: