

Submit 2 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Reg., Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO. 30-025-33148
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-155
7. Lease Name or Unit Agreement Name:  New Mexico 'O' State NCT-1
8. Well No. 38
9. Pool name or Wildcat North Vacuum Abo/Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	2. Name of Operator Texaco Exploration & Production
3. Address of Operator 500 N. Loraine Midland, Texas 79702	4. Well Location Unit Letter <u>I</u> : <u>2085'</u> feet from the <u>South</u> line and <u>710'</u> feet from the <u>East</u> line Section <u>36</u> Township <u>17-S</u> Range <u>34-E</u> NMPM County <u>Lea</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3987'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Request TA status ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 01-16-02 MIRU Key & Weatherford; TOH laying down rods, parted deep.  
01-17-02 Finish laying down rods. NDWH, NUBOP, TOH w/tbg; swab tbg, pump and in tbg.  
01-18-02 Finish TOH w/2-7/8" tbg. TIH w/4-3/4" bit, 5-1/2" csg scraper to 9200', TOH w/same. TIH w/5-1/2" pkr to 2000', SDON.  
01-21-02 Finish TIH w/5-1/2" pkr. Set @ 9115', held load test to 500 psi. TOH w/pkr, start in w/5-1/2" CIBP. Prep to set CIBP in a.m.  
01-22-02 Finish TIH w/CIBP, set @ 9115'. Circ 230 bbls of pkr fluid. Chart to 500 psi. TOH laying down 2-7/8" tbg. SD.  
01-23-02 Lay down 300 jts of 2-7/8" tbg. ND BOP. Flange well up. Rig down.

Well is temporarily abandoned.

This Approval of Temporary  
Abandonment Expires 3/7/07

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Laura Skinner TITLE Regulatory Specialist DATE 02-27-02

Type or print name Laura Skinner Telephone No. 915-687-7355

(This space for State use)

APPROVED BY \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of approval, if any:

MAR 07 2002

