

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33148
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	NEW MEXICO 'O' STATE #38 (FORMERLY VACUUM '36' STATE COM)
8. Well No.	38
9. Pool Name or Wildcat	Alaska
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3987'

SUNDRY NOTICES AND REPORTS ON WELL  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	P.O. Box 46510, Denver Colorado 80201-6510
4. Well Location	Unit Letter <u>I</u> <u>2085</u> Feet From The <u>SOUTH</u> Line and <u>710</u> Feet From The <u>EAST</u> Line Section <u>36</u> Township <u>17-S</u> Range <u>34-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3987'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	COMPLETION <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU PRIDE WS. CHANGE OUT TBG 3000# TO 5000#. NU BOP. TIH. 12-27-95.
2. TEST DV TOOL TO 4000#. TIH. TAG CMT @ 11286'. COC TO PBTD 11460'. 12-28-95.
3. TOH. LD DC. TIH W/ SN-PKR. ON/OFF TOOL, ON 2-7/8" TBG TO 11243'. SPOT 250 GAL 10% ACETIC ACID. POOH TO 10992' AND SET PKR. 12-29-96.
4. F/U SCHLUMBERGER. PERF'D W/ 2 JSPF TWICE: 11,120-11,128', 11,214-11,226'. 80 HOLES. 12-31-96.
5. FL 430 BO, 1001 MCF, FTP 1580, ON 15/64" CHOKE IN 24 HOURS. DRLG TO SI FL. 01-01-96.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham TITLE Drilling Operations Mgr. DATE 1/8/96  
TYPE OR PRINT NAME C. P. Basham Telephone No. (303)621-4851

(This space for State Use)

APPROVED BY C. P. Basham TITLE Drilling Operations Mgr. DATE JAN 30 1996  
CONDITIONS OF APPROVAL, IF ANY: None