Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office Ent	, Minerals and Natural Resources	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 87240		WELL API NO.
District II 811 South First, Artesia, NM 87210 OIL	CONSERVATION DIVISION	30-025-33329
District III	2040 Bouul 1 & Meco	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE 🗴 FEE 🗌
<u>District IV</u> 2040 South Pacheco, Santa Fe, NM 87505	[4	6. State Oil & Gas Lease No. B-155-1
SUNDRY NOTICES AND	DEDORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO I DIFFERENT RESERVOIR. USE "APPLICATION FO PROPOSALS.)	DRILL OR TO DEEPEN OR PLUG BACK TO A R PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name:
1. Type of Well:	19	Central Vacuum Unit
Oil Well X Gas Well Oth	ner	
2. Name of Operator		3. Well No.
- I	,	
Chevron U.S.A. Inc. 3. Address of Operator		2. Pool name or Wildcat
15 Smith Road - Midland, Texas 79705	`	Vacuum Grayburg San Andres
4. Well Location		Vacuum GrayDord San Altres
Unit Letter <u>M</u> : 974	feet from the <b>South</b> line and	199 feet from the West line
Section 31	Township 17-s Range 35-E	NMPM County Lea
	vation (Show whether DR, RKB, RT, GR, etc.)	
***	3977' GR	Contract of the Contract of th
11. Check Appropris	ate Box to Indicate Nature of Notice, R	enort or Other Data
NOTICE OF INTENTION	1	•
		EQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG A	ND ABANDON   REMEDIAL WORK	X ALTERING CASING
TEMPORARILY ABANDON CHANG	E PLANS COMMENCE DRILLING	G OPNS.  PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIP COMPL	ETION CASING TEST AND CEMENT JOB	
OTHER:	OTHER: convert to	flow
12. Describe Proposed or Completed Operatio of starting any proposed work). SEE RUL or recompilation.	ons (Clearly state all pertinent details, and give E 1103. For Multiple Completions: Attach w	e pertinent dates, including estimated date
03-18-02 MIRU.		
	i 80 bbls 10# brine water & 10 bbls do	was the Mire on smoothing Direct
	ing. Rigged up flow line.	war cog. 17 g on vacuum. Pumped
03-20-02 Pumped 75 bbls hot water	: 10# brine down casing & 18 bbls down	tbg. TIH w/bit & casing scraper
	TIH w/RBP & 2-3/8" tbg. Set RBP @ 42	
	: 10# brine water. Release RBP @ 4288	. TIH w/packer, SN & tbg. Set
	water. They on vacuum. Hook up flow	line. Load & test casing to
625 psi for 30 min (good 03-25-02 RD.	d). Turn well down flow line.	
Original chart w/copy attached.		
I hereby certify that the information above is true and o	complete to the best of my knowledge and belief.	
$\mathcal{L}$	•	
SIGNATURE DOUS & SRIMW	TITLE Regulatory Specia	List DATE 07-29-02
Type or print name Laura Skinner		Telephone No. 915-687-7355
(This space for State use)		** **
·	ORIGINAL SIGNED BY	<b>J</b> ŲL 3 1 2002
APPROVED BY	GARY W MANUE	DATE
Conditions of approval, if any:	OC FIELD REPRESENTATIVE II/STAFF M	AANAGET.

State of New Mexico

Form C-103

DATE 3-22-02 WELL NAME Cowland Maguin Voil "187 SUPERVISOR & Surge Manais PACKER TYPE mulcle destal Palson PACKER SETTING DEPTH 4283' PERFORATIONS 4338- 47391 9:39 CVU #/87 SEC, 31, TITS, H35E 3/22/2002 PROD PROP.