: Calculate 2 and in a		State o	of New	Mexico		
Submit 3 copies to Appropriate District Office	Er.	,, Minerals and Na	atural R	esources Department		Form C-103 Revised 1-1-89
DISTRICT I	OII	CONSERV	АТІ	ON DIVISION		
P.O. Box 1980, Hobbs, NM 882	40				WELL API NO.	
DISTRICT II		P.O. B			30-025-33329	
P.O. Box Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088					5. Indicate Type of Lease	
DISTRICT III					STATE	FEE
1000 Rio Brazos Rd., Aztec, NM	87410				6. State Oil / Gas Lease No.	
SUNDR	Y NOTICES	AND REPORTS O	N WE		B-155	<u>⊢1</u>
(DO NOT USE THIS FORM FO	R PROPOSALS	S TO DRILL OR TO I	DEEPE	N OR PLUG BACK TO A	7. Lease Name or Unit Agreeme	ot No
DIFFERENT	RESERVOIR.	USE "APPLICATION OR SUCH PROPOS	FOR F	PERMIT	CENTRAL VACUUM UNIT	nt name
	GAS -		AL3.)			
WELL		OTHER				
2. Name of Operator					8. Well No.	
TEXACO EXPLORATION & PRODUCTION INC.					187	
3. Address of Operator 205 E. Bender, HOBBS, NM 88240					9. Pool Name or Wildcat	
4. Well Location					VACUUM GRAYBURG SA	AN ANDRES
Unit Letter M	: 974	Feet From The	sou	TH_Line and 1199	Feet From The MICCT	
						_Line
Section <u>31</u>				Range <u>35-E</u> NM		COUNTY
	10. Ek	evation (Show whethe	r DF, RI	(B, RT,GR, etc.) 3989' GR		
11. Che	ck Appropria	ate Box to Indica	ite Na	ture of Notice, Report	, or Other Data	
NOTICE OF INTEI				1	BSEQUENT REPORT	
PERFORM REMEDIAL WORK		ND ABANDON				
L	1		Ц	REMEDIAL WORK		
	CHANGE	PLANS		COMMENCE DRILLING OPER		
]			CASING TEST AND CEMEN	Т ЈОВ	
OTHER:				OTHER:	FRACTURE TREATMENT	Ø
 Describe Proposed or Complete any proposed work) SEE RULE 	ted Operations E 1103.	(Clearly state all pe	ertinent	details, and give pertinent	t dates, including estimated da	te of starting
The notice of intent dated 11/8/96 to	perform this wo	orkover was approved	by the	NMOCD on 11/13/96.		
11/18/96 - 11/25/96 1. MIRU pulling unit & cable spooler						
2. TIH w/ bit, cleaned out to 4509'.						
			ickeida	w/ fresh unter		
 TIH w/ 5-1/2" pkr. Tested tbg to 8500 psi. Set pkr @ 4233, loaded backside w/ fresh water. Fracture treated perfs 4328'-4473' w/ 35,406 gals 40# YF-40 Gel, 1200# Adamite Regaine, 100,700# 16/30 Ottawa sand & 28,000# 16/30 Resin Coated sand Max P = 8600# AIR = 35 RPM. Cleaned aut conduct called the activity. 						
 Fracture treated perfs 4328'-4473 Resin Coated sand. Max P = 860 	3' w/ 35,406 gais)0# AIR = 35 BF	s 40# YF-40 Gel, 120 PM. Cleaned out sand	0# Adaı d w/ coi	nite Regaine, 100,700# 16/3 led tbg unit.	0 Ottawa sand & 28,000# 16/30	
5. Released packer & TOH w/ frac t				-	BP to 4800' (PBTD @ 4808')	
6. TIH w/ subpump & production eq				-		
OPT 12/9/96 PUMPING BY SUBPU	MP: 108 BOP), 757 BWPD, 0 MCF	۶D			
(INTERNAL TEPI STATUS REMAIN						
	NO FIVI)					
hereby certify that the information - to	(O)					
I hereby certify that the information above is true and	complete to the best			\cct		
SIGNATURE	Smy		Engr /	1001	DATE2/	18/96
TYPE OR PRINT NAME	Monte C.	Duncan			Telephone No.	397-0418
			·			
(This space for State Use)					n s	
	· · · ·	TITLE			DATE DATE	Ge REA
CONDITIONS OF APPROVAL IF ANY	•			· · · · · · · · · · · · · · · · · · ·		

CONDITIONS OF APPROVAL, IF ANY