

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

38. GEOLOGIC MARKERS			
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Upper Queen	4580'	4640'	Oil pay
Lower Queen	4740	4746'	Oil pay
Penrose 1	4853'	4860'	Oil pay
Penrose 2	4907'	4952'	Oil pay
Penrose 3	4970	4987'	Oil pay
		DEPTH	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)
		4724-4973'	1,000 gals PrePad + 2 drum Pro-Kem scale inhibitor + 100,000 gals aqua frac + 6000# 100 mesh sand + 76,000# 20/40 Brady sand and 80,000# 16/30 sand.
		4555-4621	1000 gals of 15% NeFe acid,
		4555-4621'	30,000 Gals Gel, 2800# 100 mesh Brady sand & 42700# 16/30 Brady Sand

TOP		
NAME	MEAS. DEPTH	TRUE VERT. DEPTH
Rustler	1806'	
Salado	2057'	
Yates	3540'	
Seven Rivers	3897'	
Queen	4580'	