

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-33954
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name McCallister State
8. Well No. 12
9. Pool name or Wildcat Vacuum; Abo, North

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	
2. Name of Operator Marathon Oil Company	
3. Address of Operator P.O. Box 2409 Hobbs, NM 88240	
4. Well Location Unit Letter L : 1945 Feet From The South Line and 850 Feet From The West Line Section 25 Township 17-S Range 34-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 4008 KB 4026	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: Perf Abo and DHC w/Upper Penn & Wolfcamp ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/16 MIRU PU. POOH w/rods & pump. ND wellhead. NU BOPE. POOH w/tbg. RIH w/RBP, set at 9350'. Pickle tbg w/500 gals 15% acid. Spot 250 gals 15% across 8960-9228'.
7/21 Perf 9102-03', 9108-11', 9119-32', 9135-37', 9140-43', 9147-49', 9172-74', 9184-87', 9195-9201', 9204-12', 9219-20', 9222-9224', 9227-29', 2 SPF, 120 deg phas. RIH w/pkr, set at 9049'. 7/22 Acidize 9102-9229' w/14,200 gals 15% VCA acid w/192 BS. Swab well.
7/24 Pump scale squeeze. Rel pkr. POOH.
7/25 RIH, rel RBP at 9350'. POOH. RIH w/RBP & pkr. Set RBP at 9001', pkr at 8986'. Test RBP, OK. Rel pkr. PUH. Spot 250 gals 15% acid across 8379-8558'.
7/26 Perf 8379-85', 8390-94', 8396-8402', 8406-24', 8436-38', 8451-58', 8470-72', 8477-79', 8493-95', 8502-13', 8516-22', 8529-32', 8537-44', 8547-48', 8552-8557', w/2 SPF. 7/28 Acidize 8379-8557 w/20,000 gals VCA acid & 308 BS. Swab well. 7/30 Rel pkr at 8290'. Latched on & rel RBP at 9001'. POOH w/both. ND BOPE. NU wellhead. 7/31 RIH w/pump & rods. RD PU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 9/10/98
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE