

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-34342
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name R.E. Graham 7
8. Well No. 3
9. Pool name or Wildcat North Young
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3764 DE-3777 KB-3780

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Drilling	2. Name of Operator Helmerich & Payne, Inc.
3. Address of Operator 1579 East 21st Street, Tulsa, OK 74114	4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1650</u> Feet From The <u>West</u> Line Section <u>7</u> Township <u>18S</u> Range <u>32E</u> NMPM <u>Lea</u> County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>set 8-5/8" csg</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled 11" hole to 3138'. Set 8-5/8" 32# J-55 STL casing @ 3143'. Cemented with 605 sx Class "C"+6%gel. Tailed in with 275 sx Class "C"+2%CC. No cement to surface. Ran temperature log. TOC @ 100 deg. Ran 1" pope to 100' & cement with 200 sx Class "C"+3%CC. Circ 60 sx to surface. Witnessed by Buddy Hill, State of New Mexico Representative. WOC 7 hrs. Cut off casing. Weld on 8-5/8" wellhead and test to 1000PSI. N/U BOP's. Test BOPs. Test casing to 1500 PSI for 30 minutes.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Drilling Superintendent DATE 4-1-98
TYPE OR PRINT NAME Steve Simonton TELEPHONE NO. 918-742-553

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE 4-1-98

CONDITIONS OF APPROVAL, IF ANY: