Dentante en 1	T OF THE INTERIOR LAND MANAGEMENT	Expires: March 31, 1993 5. Lease Designation and Serial No.
		NM27570
Do not use this form for proposals to dri	AND REPORTS ON WELLS III or to deepen or reentry to a different reservoir R PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name
SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
I. Type of Well Oil Gas Well Well Other		8. Well Name and No.
2. Name of Operator Matador Operating Co		Diamante Fed "21" #1 9. API Well No.
3. Address and Telephone No.		30-025-34445
310 W. Wall, Ste.906 Midland, TX 79701 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, or Exploratory Area Gem Morrow
1650 FSL; 1650 FWL Sec 21, T19S, R33E		11. County or Parish, State
		Lea Co., NM
	s) TO INDICATE NATURE OF NOTICE, REP	
TYPE OF SUBMISSION	TYPE OF ACTIO	N
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
X Subsequent Report	Plugging Back	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water (Note: Report results of multiple completion on Well
	I pertinent details, and give pertinent dates, including estimated date of star	Completion or Recompletion Report and Log form.)
 Bescribe Proposed or Completed Operations (Clearly state and give subsurface locations and measured and true vertice 	al depths for all markers and zones pertinent to this work.)*	
and a second		
 w/Schlumberger 2 1/8" Energie PU. POH w/tbg & pkr. Isolar cement. Drill out cement. Se Howco PLS pkr. Set pkr @ 1 1" / 6" Pivot guns @ 4spf (40 90% methanol and 24 bbl C02 plug to 3100, OK. Perf Morr all @ 6spf (291 holes). Acid - 13,520' w/50000 lbs 20/40 l Flow test well till 12/11/98. F 	Well depleted zone from 13,238-59. Perf Morrow freet. Flow test until 10/30/98. No increase from new p te perfs 13,238-59 and squeeze same w/60 sxs cemen t Howco BWB permanent pkr @ 13,550'. RIH w/41 3,270'. Tree up test pkr, tbg and tree OK. Perf Morr holes). Acidize perfs 13,570-80' w/1000 gals 10% a 2. No flow. Set plug in XN nipple in lower pkr asser row from 13,510-20', 13,404-414', 13,365-378', 13 w/5000 gal Mod 101 + C02. LD 2 7/8" tbg. PU 3 $\frac{1}{20}$ bauxite + 13,314 gals 20 lb Xlink Binary @ 20 BPM Pull 3 $\frac{1}{20}$ " tbg. RIH w/2 7/8" tbg as before. Perf Morr 189 w/4spf (25 holes). Turn well down sales line for the same set of the same same sales line for the same set of the same set.	erfs. Kill well. MIRU t. Drill out CR & 9 jts 2 7/8" L-80 tbg and row from 13,570-80' w/ acetic acid containing nbly @ 13,557'. Test ,349-358', 13,420-26', 2" tbg. Frac perfs 13,349 FOTED FOR, BECORD
14. I hereby reméy that the foregoing is true and correct Signed	Title Russ Mathis - Prod. Manag	ger _{Date} 2/9/99
(This space for Federal or State office use)	e e e e e e e e e e e e e e e e e e e	
Approved by Conditions of approval, if any:	Title	Date
	knowingly and willfully to make to any department or agency of the Un	ited States any false fictitious or fraudulent stateme
or representations as to any matter within its jurisdiction.		

÷