

LINE	RATE 1		RATE 2		RATE 3		RATE 4		
	1ST	2ND	1ST	2ND	1ST	2ND	1ST	2ND	
1 QM	0.156	0.156	0.000	0.000	0.000	0.000	0.000	0.000	Pc2/(Pc2-Pw2) = 1.481
2 TW	534	534	534	534	534	534	534	534	ERR
3 Ts	660.0	660.0	660.0	660.0	660.0	660.0	660.0	660.0	ERR
4 T	597.0	597.0	597.0	597.0	597.0	597.0	597.0	597.0	ERR
PR (est)	1.39		0.00		0.00		0.00		ERR
5 Z(est)	0.848	0.825	ERR	ERR	ERR	ERR	ERR	ERR	ERR
6 TZ	506.0	492.5	ERR	ERR	ERR	ERR	ERR	ERR	
7 GH/TZ	18.321	18.823	ERR	ERR	ERR	ERR	ERR	ERR	AOF= Q 0.231
8 eS	1.988	2.026	ERR	ERR	ERR	ERR	ERR	ERR	ERR
9 l-e-S	0.497	0.506	ERR	ERR	ERR	ERR	ERR	ERR	ERR
0 Pt	935.2	935.2	0.0	0.0	0.0	0.0	0.0	0.0	ERR
1 Pt2 /1000	874.6	874.6	0.0	0.0	0.0	0.0	0.0	0.0	
2 Fr	0.011925	0.011925	0.011925	0.011925	0.011925	0.011925	0.011925	0.011925	
3 Fc=FrTZ	6.035	5.874	ERR	ERR	ERR	ERR	ERR	ERR	
4 FcQm	0.94	0.92	ERR	ERR	ERR	ERR	ERR	ERR	
5 L/H(FcQm)	0.9	0.8	ERR	ERR	ERR	ERR	ERR	ERR	
6 Fw	0.440388	0.425104	ERR	ERR	ERR	ERR	ERR	ERR	
7 Pw2	875.0	875.0	ERR	ERR	ERR	ERR	ERR	ERR	
8 Ps2	1739.4	1772.4	ERR	ERR	ERR	ERR	ERR	ERR	
9 Ps	1318.9	1331.3	ERR	ERR	ERR	ERR	ERR	ERR	
0 P	1127.0	1133.3	ERR	ERR	ERR	ERR	ERR	ERR	
1 Pr	1.67	1.68	ERR	ERR	ERR	ERR	ERR	ERR	
2 Tr	1.50	1.50	1.50	1.50	1.50	1.50	1.50	1.50	
3 Z	0.825	0.824	ERR	ERR	ERR	ERR	ERR	ERR	

FORM C122-D