

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-35628

5. Indicate Type of Lease

STATE ☒FEE ☐

6. State Oil / Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.3. Address of Operator
PO BOX 3109, MIDLAND, TX 79702

4. Well Location

Unit Letter F : 2100 Feet From The NORTH Line and 1390 Feet From The WEST LineSection 31 Township 17-S Range 35-E NMPM LEA COUNTY10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3973'7. Lease Name or Unit Agreement Name
CENTRAL VACUUM UNIT8. Well No.
2649. Pool Name or Wildcat
VACUUM GRAYBURG SAN ANDRES

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐CASING TEST AND CEMENT JOB ☐OTHER: ☐ COMPLETION DATA ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-01-01: RU TO RUN GR/CCL. UNABLE DUE TO FAULTY LINE FOOTAGE COUNTER. TIH W/GR/CCL & CORRELATE TO CNL OPEN HOLE LOG. PBTD @ 4624. LOG TO 3480. TIH W/7" CIBP & SET @ 4545. TOP OF WHIP & KOP @ 4530. 9-06-01: MIRU KEY #118 HORIZONTAL RIG. 9-07-01: TIH W/WHIPSTOCK. SET @ 256.5 AZ. MILL 4529-4530, 4531, 4537 + 3' FORMATION TO 4540. TOW @ 4529, BOW @ 4537. 9-09-01: SLIDE FR 4540-4572, 4692, 4870, 4917, 4943, 5022, 5036, 5106, 5124, 5233, 5243, 5326, 5336, 5419, 5427, 5545, 5555, 5608, 5628, 5750, 5765, 5798, 5813, 5830, 5845, 5860, 5892, 6460, 6707. TIH W/RBP TO SET ABOVE WINDOW @ 4437. RIG RELEASED @ 1300 HRS 9-14-01. 9-18-01: MIRU COMPLETION RIG #291. PU RBP RETR HEAD & TIH W/135 JTS TBG. STOP @ 100' ABOVE RBP @ 4437. REL RBP. PU 2 7/8" TNBG. TIH ON 3 1/2" FRAC STRING. SET PKR & TEST TO 1000 PSI. SN @ 4426. 9-25-01: ACIDIZE LATERAL W/40,000 GALS 20% HCL & 15,000 GALS WF130 + 12390 GALS OF SCALE INHIB. REL PKR. 9-26-01: TAG CIBP @ 4545. TIH AFTER GETTING THRU WINDOW. TAG FSH @ 5811. 9-27-01: TRY TO KNOWK OUT CIBP @ 4545. BUST UP & MOVE CIBP TO 4570. 9-28-01: C/O FR 4570-4629. 9-29-01: TIH W/PUP JOINTS, 2 7/8" TBG @ 4491. HU ELEC & STARTED UP PUMP @ 1700 HRS. PUMP TO BTRY. 9-30-01: PUMP 24 HRS. NEW OIL.

10-02-01: ON 24 HR OPT. PUMPED 181 BO, 2200 BW, 382 MCF.

PBTD: 4629, TOW @ 4529, BOW @ 4537

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering AssistantDATE 10/17/01TYPE OR PRINT NAME J. Denise LeakeTelephone No. 915-688-4752

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: TITLE DATE 10/20/2001

DeSoto/Nichols #2-11-10