

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-35698
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: TMBR "14" State
7. Well No. 4
9. Pool name or Wildcat Vacuum, Blinebry, NE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
TMBR/Sharp Drilling, Inc.

3. Address of Operator
P. O. Drawer 10970, Midland, TX 79702

4. Well Location

Unit Letter O : 990 feet from the South line and 1650 feet from the East line

Section 14 Township 17S Range 35E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
GR 3927'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Bradenhead Squeeze ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

See attached sheet.

RECEIVED
Hobbs
OCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Production Manager DATE 02/26/03

Type or print name Lonnie Arnold ORIGINAL SIGNED BY GARY W. WINK Telephone No. (915) 699-5050
(This space for State use)

APPROVED BY [Signature] TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE MAR 04 2003

Conditions of approval, if any:

TMBR/SHARP DRILLING, INC.

TMBR "14" State No. 4

990' FSL & 1650' FEL

Sec. 14, T-17S, R-35E

Lea County, NM

BRADENHEAD SQUEEZE

- 02/04/03 PO: Prep to bradenhead squeeze.
MIRU TWS. POH w/rods & pump. ND WH, NU BOP, release TAC. POH. GIH w/RBP & pkr. Set RBP @ 6400', set pkr @ 6369'. Load tbg w/2% KCL, press to 500 psi, ok. Circ hole w/2% KCL, press annulus to 500 psi, ok. Secure well.
- 02/05/03 PO: Prep to POH w/RBP.
SICP 0 psi, SI bradenhead press 790 psi. POH w/pkr. RU BJ Service. Load 5½" csg, press to 500 psi. Bled down bradenhead. Pump 50 sx CI "H" thickset 14.6 ppg, 1.5 cu.ft. yield, 250 sx CL "C" Neat, 14.8 ppg, 1.33 cu.ft. yield, 2 BPM, 1125 psi. SD ¼ hr. Pump 20 sx CI "C" 2% CaCl2. Flush w/1 BFW. Hold 688 psi steady. RD BJ. Secure well.
- 02/26/03 PO: On production.
SICP 0 psi. SI bradenhead 100 psi. Bled down bradenhead in 1 min, no blow or flow. GIH w/retrieving tool, release RBP. POH. GIH w/SN & TAC. ND BOP, set TAC, NU WH. GIH w/rebuilt pump & rods, space out. Load tbg w/18 BBL 2% KCL & press to 500 psi, ok. Stroke unit, 5 strokes, 500 psi, ok. Left on POC. Turn over to pumper. No change in tbg or rod detail.
FINAL REPORT.

RECEIVED
FEB 26 2003