Form 3160-5 (August 1999)

United States Department of the Interior

Rureau Of Land Management

Form Approved OMB No. 1004-0135 Expires November 30, 2000

Bureau Of Land Management			5. Lease Serial No.	
Sundry Notices And Reports on Wells			NM56749	
Do not use this form for proposals to drill or to re-enter an Abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name	
			7. If Unit or CA/Agreement, Name and/or No.	
			29406	
SUBMIT IN TRIPLICATE - Other Instructions On reverse side			8. Well Name and N	10.
1. Type of Well: ☑ Oil Well □ Gas Well □ Other			Federal USA L #10	
✓ Oil Well ☐ Gas Well ☐ Other 2. Name of Operator			9. API Well No.	
Concho Oil & Gas Corp.			30-025-35912	
3. Address of Operator 3b. Phone No. (Include area code)			10. Field and Pool, or Exploratory Area	
110 W Louisiana, Ste 410 Midland, Texas 79701 (915) 683-7443			Tonto-Seven Rivers 11. County or Parish, State	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County of Latish, State	
990' FNL & 530' FWL, Sec 14, T19S, R33E			Lea Co, NM	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
Type Of Submission	Type Of Action			
	☐ Acidize ☐ Deepen	☐ Produc	ction (Start/Resume)	☐ Water Shut-Off
☐ Notice of Intent	☐ Alter Casing ☐ Fracture To	reat 🗌 Reclai	mation	☐ Well Integrity
	☐ Casing Repair ☐ New Const	truction Recon	nplete	Ø Other —
☐ Final Abandonment Notice	☐ Change Plans ☐ Plug and A		orarily Abandon	Completion
	☐ Convert to Injection ☐ Plug Back	_	Disposal	
13. Describe proposed or completed operations. (clearly state all pertinent details, starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 7/18/02- RU Key Unit. RU WH & BOP. Ran GR/CCL/CBL from 3815'-2500'. Perf from 3708'-3730' w/1 SPF. TIH w/pkr & tbg. 7/19/02- Circ well. Set pkr. Press annulus to 510 psi. Swab well. 7/21/02- Swab well. TIH w/collar, jt, SN, 2 7/8" tbg, sub, WH & vlv. 7/22/02- Swab well. FL @ 3400'. Release pkr. TOH w/pkr & tbg. TIH w/collar, tbg, SN, sub, WH & vlv. 7/23/02- Frac perfs w/18,500 gals 30# x-linked gel, 33,000# 16/30 sd & 10,000# 16/30 resin coated sd. 7/24/02- Well on vac. Tagged @ 3733'. Wash out. Remove BOP. Hook up WH. Started swab test. Put on 8/64" chk. Open well to test tank overnight. 7/25-26/02- Swabbed well. 7/29/02- Well flwg. RD & cleaned location. 8/3/02- PU & RIH w/pmp & rods. Set 2 ½ x 1.5 x 16 RWBC pmp. Loaded & tested. Started pmpg.				
14. I hereby certify that the foregoing in Name (Printed/Typed)			Q B	
Dora Bustamante		Title Productio	n Analyst \	Care Sile
Signature Warn Bustamanto Date 08/13/02				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
		77.4		
Approved by Conditions of approval, if any, are attached.	Approval of this notice does not warrant or	Title	I Da	te
Certify that the applicant holds legal or equit Whick would entitle the applicant to conduct	table title to those rights in the subject lease	Office		