Form 3160-5 (August 1999)

## Inited States Depairment of the Interior

Bureau Of Land Management

**Sundry Notices And Reports on Wells** Do not use this form for proposals to drill or to re-enter an

Abandoned well. Use form 3160-3 (APD) for such proposals.

Expires November 30, 2000

	-
5. Lease Serial No.	
NM-36915	_
6. If Indian, Allottee or Tribe Name	

7. If Unit or CA/Agreement, Name and/or No.

Form Approved

OMB No. 1004-0135

00	JE	ومسارهون	- 17	TIAL	
W	V.	ا سا ادا		IAI	

SUBMIT IN TRIPLICATE - Other	r Instructions On reve	rse side		8. Well Name and I	٧o.	
1. Type of Well:						
1 / 2	☐ Other			Gantryperson #1		
2. Name of Operator				9. API Well No.		
Concho Oil & Gas Corp.				30-025-35943		
3. Address of Operator		No. (Include area code)		10. Field and Pool, or Exploratory Area		
110 W Louisiana, Ste 410 Midland	, Texas 79701	(915) 683-7443		Tonto-Seven Rivers		
4. Location of Well (Footage, Sec., T.,	R., M., or Survey Descrip	ption)		11. County or Paris	n, State	
990' FNL & 2310' FWL, Sec 15, T19S, R33E			Lea Co, NM			
12. Check	Appropriate Box to	Indicate Nature of N	lotice, Re	eport or Other Dat	a	
Type Of Submission		Ту	pe Of Ac	ction		
1,750	☐ Acidize	Deepen	☐ Produ	iction (Start/Resume)	☐ Water Shut-Off	
□ Notice of Intent	☐ Alter Casing	☐ Fracture Treat	Recla	amation	☐ Well Integrity	
Subsequent Report	☐ Casing Repair	☐ New Construction	Reco	mplete	Other ———	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☐ Tem	porarily Abandon	Completion	
	☐ Convert to Injection	☐ Plug Back	☐ Wate	r Disposal		
13. Describe proposed or completed operations. (clearly state all pertinent details, starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)						
7/30/02- Installed WH & BOP. Per						
7/31/02- Pmp & spot annulus, press	s to 500 psi. Acidize w	/1800 gals 7 ½% NEF	E & 75 B	BS.		
8/1/02- POH w/pkr. TIH w/notched	d collar, 2 7/8" tbg, SN	. EOT 3543'.				

@ 3632'. Remove BOP. Install WH. Swab. IFL @ 500'. 8/6/02- Open well to test tank on a 20/64" chk & flowed 1 hr & swab well.

8/2/02- Frac treated perfs w/18,500 gals 30# X-linked gel, 33,000, 16/30 sand & 10,000# 16/30 resin sand.

8/7/02- Swabbed well.

8/8/02- Open well & flowed 2 hrs. TIH w/rods & pmp. Released unit.

			The state of the s	
14. I hereby certify that the foregoing is true and correct Name ( <i>Printed/Typed</i> )			, and the second se	
Dora Bustamante	Title Production A	nalyst	<i>მე</i> ე	
Signature Wara Bartamant	Date 08/12/02	Ü	03 sagos	(i) (ii)
THIS SPACE FOR FEDERAL OR S	STATE OFFICE USE	(6)	Could Alle	
Approved by	Title		Date	رق
Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease Whick would entitle the applicant to conduct operations thereon.	Office		Sex STSTING	

8/5/02- Remove frac vlv. Install BOP & TIH w/tbg. Tagged fill @ 3812'-276' rat hole. Pulled back to 3631'. EOT @3664' & SN