


$\frac{1}{2} \times \frac{1}{2} = \frac{1}{4}$



|                     |             |           |                    |            |       |
|---------------------|-------------|-----------|--------------------|------------|-------|
| Company             | Cotton      |           |                    |            |       |
| Farm Name           | Grubbs-7    |           |                    | Well No. 1 |       |
| Land Classification | Government  |           |                    |            |       |
| Sec.                | 7           | Twp.      | 20                 | Range      | 55    |
|                     |             |           |                    | County     | Lea   |
| Feet from Line:     | N.          | 100       | S.                 | E. 1200    | W.    |
| Elevation           | Method      |           |                    |            |       |
| Contractor          | J. H. Smith |           |                    |            | Scout |
| Spudded             | 7/1/20      | Completed | Initial Production |            |       |
| Bond Status         |             |           |                    |            |       |

[illegible]

**Tubing Record**

---

---

**Packer**

## ACID RECORD

| Gals.   |    |
|---------|----|
|         |    |
|         |    |
|         |    |
|         |    |
| Top Pay | TD |

|     |
|-----|
| TA  |
| TX  |
| BX  |
| TRS |
| TY  |
| TBL |
| TWL |

## SHOOTING RECORD

| No. of Quarts | From | To |
|---------------|------|----|
| No. of Quarts | From | To |
| S/12, 475-505 | S/   | S/ |
| S/12, 475-505 | S/   | S/ |

[illegible]

## LOG

[illegible]