Form 9-331 a. (Feb. 1951)					
		×			

(SUBMIT IN TRIPLICATE)
HOBBS OF THE OCC

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY OUT 15

SUNDRY NOTICES A	AND REPORTS ON WELLS		
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF		
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO CHARGE FEATURE NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL			
NOTICE OF INTENTION TO RE-DRILL OR REPRIN WELL-	1 1		
NOTICE OF INTENTION TO SHOOT OF ACIDIZE	SUPPLEMENTARY WELL HISTORY		
1	Subsequent Report of Abandon- x		
NOTICE OF INTENTION TO ABANDON WELL	ment		
(INDICATE ABOVE BY CHECK MAR	K NATURE OF REPORT, NOTICE, OR OTHER DATA)		
	Midland, Fexas 10/14, 19 57		
Swell H. Suse, Jr Federal	ഷ് നൂറ		
Well No. 1 is located 660 ft. from	$\begin{bmatrix} \mathbb{N} \\ \mathbb{N} \end{bmatrix}$ line and 1926 . \mathbb{N} from $\begin{bmatrix} \mathbb{N} \\ \mathbb{W} \end{bmatrix}$ line of sec. \mathbb{N}		
S34 884 Sec. 7 20-8	33-2 Mali in		
(½ Sec. and Sec. No.) (Twp.)	(Range) (Meridian)		
Lea Lea	New Mexico		
H1deat (Field) (County	y or Subdivision) (State or Territory)		
(State names of and expected depths to objective sands; show s ing points, and al	evel 18 _222& ft. AILS OF WORK sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement- lother important proposed work) PB-7, 190		
well was plugged and abandone	d as follows.		
 50 ax cement plug of salt). 15 ax cement at surf 	7118-7128, 7140-7160. 2600' (base of salt) and at 1250' (top ace.		
5. Installed well marks	er and eleaned location.		
	in writing by the Geological Survey before operations may be commenced.		
Company The Texas Company			
Address	-		
idland, Texas	By Coo Los		

Title