

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

N.M.O.C.D. COPY

SUBMIT IN TRIPLICATE
(Other Instruct on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 05148

6. INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Water Injection Well

2. NAME OF OPERATOR
Anadarko Production Company

3. ADDRESS OF OPERATOR
P O Box 806 Eunice, New Mexico 88231

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At Surface
660' FSL & 660' FWL
Sec 11, T 20S, R 33E
Lea Co, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)
3540 GR

7. UNIT AGREEMENT NAME

Teas Yates Unit

8. FARM OR LEASE NAME

Tract 13

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Teas Yates Seven River

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

11 - 20S - 33E

12. COUNTY OR PARISH

Lea

13. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

☐ TEST WATER SHUT OFF

☐ FRACTURE TREAT

☐ SHOOTING OR ACIDIZING

☐ CHANGE WELL

☐ PILE OR ALTER CASING

☐ MULTIPLE COMPLETE

☐ ABANDON*

☐ CHANGE PLANS

☒ Clean out & resume wtr ☒

SUBSEQUENT REPORT OF:

☐ WATER SHUT OFF

☐ FRACTURE TREATMENT

☐ SHOOTING OR ACIDIZING

☐ (Other)

☐ REPAIRING WELL

☐ ALTERING CASING

☐ ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or 10-completion Report and Log form.)

16. REPORT OF WORK (If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. RUPU. TOH w/2 3/8" PVC lined tubing and inj PKR.
2. TIH w/3 1/2" bit on 6 2 7/8" D C & 2 7/8" tubing.
3. CO inside 4" liner from 3263 to PBTD 3354.
4. TOH w/bit
5. TIH w/5 1/2" inj PKR on 2 3/8" PVC lined tubing.
6. Load backside w/PKR fluid. (Chemical laden fresh water)
7. Set PKR @ 3150 w/10 points tension
8. RDPU and resume water inj.
9. Will dig workover pit measuring approx 10' x 20' within well pad area. Will fill and level when job is completed.

This project will not require that any other surface area be disturbed.

U.S. GEOLOGICAL SURVEY
NEW MEXICO

17. I hereby certify that the foregoing is true and correct

SIGNED John C. English

TITLE Area Supervisor

DATE 8-19-80

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF ADEQUACY, IF ANY:

TITLE

*See Instructions on Reverse Side

DATE
APPROVED
OCT 28 1980
for DISTRICT SUPERVISOR