Form 9-331 (May 1963)

14. PERMIT NO.

16.

## UN. ZD STATES DEPARTMENT OF THE INTERIOR (Other Instructions on re-

CEOLOGICAL SUBVEY

SUBMIT IN TRIPL TE\*

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

LC 065 447 6. IF INDIAN, ALLOTTEE OR TRIBE NAME

GEOEGGICAE SURVEY			
 		<del></del>	

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME GAS WELL Water Injection Well WELL Teas Yates Unit OTHER 2. NAME OF OPERATOR Anadarko Production Company Tract 3 9. WELL NO. 3. ADDRESS OF OPERATOR

Eunice, New Mexico 88231 P.O. Box 806 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)

At surface

990' FNL & 1650' Sec 13, T 20S, R 33K

Lea County, NM

wuv z 0 1980

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3608' GRU. S. GEOLOGICAL SURVEY 13-20S-33E 12. COUNTY OR PARISH 13. STATE

10. FIELD AND POOL, OR WILDCAT Teas Yates Seven Rive

11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA

Lea

N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PULL OR ALTER CASING

ABANDON\* CHANGE PLANS SUBSEQUENT REPORT OF:

WATER SHUT-OFF FRACTURE TREATMENT

SHOOTING OR ACIDIZING (Other) C O & return to wtr in

REPAIRING WELL

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*
  - RUPU. TOHw/2-3/8" PVC lined tubing & Inj. PKR. 1.
  - TIH w/3=7/8" bit & 2-7/8" tubing. 2.
  - CO inside 42" casing from 3350' to PBID 3388'. 3.
  - 4. TOH w/bit.

TEST WATER SHUT-OFF

FRACTURE TREAT

(Other)

SHOOT OR ACIDIZE

- 5.
- TIH w/4%" PKR on 2-3/8" PVC lined tubing. Load backside w/PKR fluid (Chemical laden fresh wtr.) 6.
- 7. Set PKR @3186' w/10 points tension.
- 8. RDPU. Resume wtr inj. 9-22-80
- WO pit filled & leveled.

18. I hereby certify that the foregoing is true and correct  SIGNED CLASSICAL	TITLE Area Supervision	DATE 11-19-88
(This space for Federal or State office use)  APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	ACCEPTED FOR RECORD.

\*See Instructions on Reverse Side

U.S. GEOLÓGICAL SURVEY

ROSWELL, NEW MEXICO