

TRIPPLICATE

NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

RECEIVED

APR 27 1951

**OIL CONSERVATION COMMISSION
HOBBES OFFICE**

Submit this report in triplicate to the Oil Conservation Commission District Office. It should be signed and filed as a report on beginning drilling operations, results of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	x	REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			

April 26, 1951

Date

Artesia, New Mexico.

Place

Following is a report on the work done and the results obtained under the heading noted above at the

Resler & Sheldon

Magnolia State

Well No. 1 in the

Company or Operator

Lease

NE 1/4

of Sec. 36

T. 20S

R. 33 E

N. M. P. M.

Wildcat

Pool

Lea

County.

The dates of this work were as follows:

Notice of intention to do the work was (~~was not~~) submitted on Form C-102 on April 20, 1951, 19____, and approval of the proposed plan was (~~was not~~) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Cement Plug was drilled after allowing cement to set 60 hours. On bailing test hole checked dry, therefore drilling was resumed.

Witnessed by R. A. Thomas R. A. Thomas Owner
Name Company Title

APPROVED:
OIL CONSERVATION COMMISSION

Ray Yurkrough
Oil & Gas Inspector

Name

Title

APR 30 1951

Date

I hereby swear or affirm that the information given above is true and correct.

Name



Vilas P. Sheldon

Position

Partner

Representing Resler & Sheldon
Company or Operator

Address Carpenter Building, Artesia, New Mexico.



100 100 100 100
100 100 100 100
100 100 100 100