DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF THE
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.		SUBSEQUENT REPORT OF WATER SHUT-OFF SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF REDRILLING OR REPAIR SUBSEQUENT REPORT OF ADMINISTRATION OF ALTERING OR REPAIR
NOTICE OF INTENTION TO PULL OR ALTER CASING	1 1	SUBSEQUENT REPORT OF ABANDONMENTSUPPLEMENTARY WELL HISTORY
(INDICATE ABOVE BY CHECK MAR	K NATUR	RE OF REPORT, NOTICE, OR OTHER DATA)

America D		November 4	10 <b>52</b>
Well No is loc	ated 2310 ft. from $S$ line and 20-S 34-E	. 1650 XX.	, 1902
SE of NW Sec. 35	20-S	ft. from   line of	sec. 35
Lynch (% Sec. and Sec. No.)	(Twp.) (Range)	M. M. P. M.	
(Field)	Lea	(Meridian) New Mexico	
The elevation of the derrick f	(County or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is 3749 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work) Will set oil string 5-1/2" Casing, 14# J-55 Black Seamless at 3682',

cement and circulate to top. Will run casing November 6, 1952.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company J. H. Elder Address Box 950 Midland, Texas Title.