Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89
DISTRICT   P.O. Box 1980, Hobbs, NM 88240 DISTRICT II	P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO.
P.O. Drawer DD, Artesia, NM 88210  DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410			Indicate Type of Lease     STATE X FEE      G. State Oil & Gas Lease No.
DIFFERENT RESER	101) FOR SUCH PROPOSALS.)	OD DI LIC DACK TO A	7. Lease Name or Unit Agreement Name  W. Pearl Queen Unit
ARMSTRONG ENERGY CO  3. Address of Operator P.O. Box 1973, Rost  4. Well Location	ORPORATION	38201	8. Well No. 122 9. Pool name or Wildcat Pearl Queen
Unit Letter J :1980   Feet From The South   Line and1980   Feet From The East   Line			
NOTICE OF INTERPRETATION OF THE PROPERTY ABANDON OTHER:  12. Describe Proposed or Completed Operation work) SEE RULE 1103.  05-10-89 P.O.H. with set it at of packer Held fine.	PLUG AND ABANDON  CHANGE PLANS  DIS (Clearly state all pertinent details, and the packer and tubing 4548'. Pulled up fluid. Tested cas: POH with tubing, well off. The pre-	REMEDIAL WORK  COMMENCE DRILLING  CASING TEST AND CEN  OTHER: Tempor  d give pertinent dates, including  Went back  3' and circula  ing annulus at	SEQUENT REPORT OF:  ALTERING CASING  OPNS. PLUG AND ABANDONMENT  MENT JOB  Cary Abandonment
hereby certify that the information above is true an	d complete to the best of my knowledge and b	લોઈ.	

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

SIGNATURE

TITLE

Agent

DATE

05-15-89

TYPE OR PRINT NAME

Orig. Signed by

Paul Kautz

Geologist

MAY 1 7 1989

CONDITIONS OF AFTROVAL, IF ANY:

- DATE -

RECEIVED

MAY 1 6 1989

OCD HOBBS OF HEE

