

NEW MEXICO OIL CONSERVATION COMMISSION Santa F. New Michoo OCC

1958 AUG 5 PM 07

Mail to District Office, Oil Conservation Commission, to which Form C-101 was sent not later than twenty days after completion of well. Follow instructions in Rules and Regulations of the Commission. Submit in QUINTUPLICATE.

If State Land submit 6 Copies

.....Depth Cleaned Out.....

| | Cabot | | Gompan | Y | | S | tate of No | Mexico "G" |
|---|--|--------------------------|--|---|---|---|---|--|
| | 6 | - | gur () | | | | | |
| ell No | | | | | | | | , r35=E, nmf |
| •••••• | 440 | | | | | | | Cou |
| | | | | | | | | m |
| Section | | | | | | | | |
| | | | | | | | | O, 195 |
| ame of Dr | illing Contra | actor | Robinso | on Bros. | | | ******** | *************************************** |
| ddress | 122 A1 | len B | rilding, | Midland, | Texas | ************************* | ***************************** | |
| levation ab | iove sea level | at Top | of Tubing He | ad | 3729 | The inf | formation given | is to be kept confidential u |
| | | | | | | | _ | • |
| | | | | | DIL SANDS OR Z | OVE | | |
| o. 1, from. | 47 | 30 | | | | | | to |
| - | 48 | <u>ح</u> | to |),862 | No. 4 | , irom | ···· | to |
| | | <u>ہے</u> اد | | | | | | |
| o. 3, from | وبا | <u></u> | to | 47.27 | No. 6 | , from | ******************************* | to |
| | | • | | IMP | DRTANT WATER | SANDS | | |
| clude data | on rate of | water inf | low and elev | ation to whic | h water rose in hol | e. | | |
| o. 1, from | | •••••• | | to | ••••• | | feet | |
| o. 2, from | | | | to | *************************************** | | feet | |
| | | | | | *************************************** | • | | |
| | | | | | | | | |
| o. 3, from | | •••••• | *************************************** | to | | •••••• | feet | |
| o. 3, from | | •••••• | *************************************** | to | | | feet | , |
| o. 3, from | | | | to | | | feet | |
| o. 3, from o. 4, from | | нт | *************************************** | to | CASING RECO | | feet | |
| o. 3, from | WEIG | HT | NEW OR USED | toto | CASING RECO | RD CUT AND | fcet | |
| o. 3, from o. 4, from | WEIG PER F | HT | NEW OR USED | toto | CASING RECO | RD CUT AND | fcet | DNS PURPOSE |
| o. 3, from o. 4, from | WEIG PER F | HT | NEW OR USED | toto | CASING RECO | RD CUT AND | fcet | ons purpose Surface Casin |
| o. 3, from o. 4, from | WEIG PER F | HT | NEW OR USED | toto | CASING RECO | RD CUT AND | fcet | ons purpose Surface Casin |
| o. 3, from o. 4, from | WEIG PER F | HT | NEW OR USED | AMOUN 301 | CASING RECO | CUT AND PULLED FROM | fcet | ons purpose Surface Casin |
| o. 3, from | WEIG PER F | HT | New or Used | AMOUN 301 | CASING RECO | CUT AND PULLED FROM | fcet | ons purpose Surface Casin |
| 8-5/8 ⁸ SIZE OF HOLE | SIZE OF CASING | HIT OOT 32# | New OR USED New New Text | AMOUNT 301 4911 | CASING RECO KIND OF SHOE Baker Howco G AND CEMENT | CUT AND PULLED FROM | PERFORATIO | Surface Casin Oil String |
| 8-5/8 ⁸ SIZE OF HOLE | VEIG PER S 2145 1145 SIZE OF CASING | WHII | New OR USED New New Or | MUDDING NO. SACES F CEMENT | CASING RECO RIND OF SHOE Baker Howco G AND CEMENT METHOD USED | CUT AND PULLED FROM ING RECORD | PERFORATIO | Surface Casin Oil String |
| 8-5/8 ^N 5-1/2 ^N SIZE OF HOLE | SIZE OF CASING | 32# WHI SE | New OR USED New New Or | AMOUNT 301 4911 MUDDING NO. SACKS F CEMENT | CASING RECO KIND OF SHOE Baker Howco G AND CEMENT METHOD USED Pump & Plug | CUT AND PULLED FROM ING RECORD | PERFORATIO | Surface Casin Oil String |
| 8-5/8 ⁸ SIZE OF HOLE | SIZE OF CASING | 32# WHI SE | New OR USED New New O | MUDDING NO. SACKS F CEMENT 300 200 | CASING RECO KIND OF SHOE Baker Howco G AND CEMENT METHOD USED Pump & Plug Pump & Plug | CUT AND PULLED FROM ING RECORD | PERFORATIO | Surface Casin Oil String |
| 8-5/8 ⁸ SIZE OF HOLE | SIZE OF CASING | 32# WHI SE | New OR USED New New O | MUDDING NO. SACKS F CEMENT 300 200 | CASING RECO KIND OF SHOE Baker Howco G AND CEMENT METHOD USED Pump & Plug | CUT AND PULLED FROM ING RECORD | PERFORATIO | Surface Casin Oil String |
| 8-5/8 ⁸ SIZE OF HOLE | SIZE OF CASING | WHIT 000T 32# | New OR USED New New 1 | MUDDING NO. SACKS F CEMENT 300 200 | CASING RECO KIND OF SHOE Baker Howco G AND CEMENT METHOD USED Pump & Plug Pump & Plug | CUT AND PULLED FROM ING RECORD G AND STIMULAT | PERFORATIO MUD RAVITY | Surface Casin Oil String AMOUNT OF MUD USED |
| 8-5/8 ⁸ 5-1/2 ⁸ SIZE OF HOLE | SIZE OF CASING | WHIT 000T 32# | New OR USED New New 1 | MUDDING NO. SACKS F CEMENT 300 200 | CASING RECO KIND OF SHOE Baker Howco G AND CEMENT METHOD USED Pump & Plug Pump & Plug Pump & Plug | CUT AND PULLED FROM ING RECORD G AND STIMULAT | PERFORATIO MUD RAVITY | Surface Casin Oil String AMOUNT OF MUD USED |
| 81ZE 8-5/8* 5-1/2* 81ZE OF HOLE 124* 7-7/8* | SIZE OF CASING 8-5/89 5-1/29 | WHI 32# 30 1,91 | New OR USED New New 12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | MUDDING MUDDING MUDDING SECORD OF ROCCESS used, I | GAND CEMENT Baker Howco GAND CEMENT METHOD USED Pump & Plug Pump & Plug | CUT AND PULLED FROM ING RECORD GI AND STIMULAT Lused, interval | PERFORATION MUD RAVITY TION treated or shot. | Surface Casin Oil String AMOUNT OF MUD USED |
| SIZE 8-5/8* 5-1/2* SIZE OF HOLE 124* 7-7/8* | SIZE OF CASING 8-5/89 5-1/29 | WHI 32# 30 1,91 | New OR USED New New 12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | MUDDING MUDDING MUDDING SECORD OF ROCCESS used, I | CASING RECO KIND OF SHOE Baker Howco G AND CEMENT METHOD USED Pump & Plug Pump & Plug Pump & Plug | CUT AND PULLED FROM ING RECORD GI AND STIMULAT Lused, interval | PERFORATION MUD RAVITY TION treated or shot. | Surface Casin Oil String AMOUNT OF MUD USED |
| SIZE 8-5/8* 5-1/2* SIZE OF HOLE 124* 7-7/8* | SIZE OF CASING 8-5/89 5-1/29 | WHI 32# 30 1,91 | New OR USED New New 12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | MUDDING MUDDING MUDDING SECORD OF ROCCESS used, I | GAND CEMENT Baker Howco GAND CEMENT METHOD USED Pump & Plug Pump & Plug | CUT AND PULLED FROM ING RECORD GI AND STIMULAT Lused, interval | PERFORATION MUD RAVITY TION treated or shot. | Surface Casin Oil String AMOUNT OF MUD USED |
| size 8-5/8" 5-1/2" Size of Hole 124" 7-7/8" | SIZE OF CASING 8-5/89 5-1/29 | WHIT 1007 32# 30 1491 | New OR USED New New New OR USED Record the Property of the P | MUDDING NO. SACES F CEMENT 300 200 EECORD OF | GAND CEMENT Baker Howco GAND CEMENT METHOD USED Pump & Plug Pump & Plug | CUT AND PULLED FROM ING RECORD GI AND STIMULAT Lused, interval | MUD RAVITY TON treated or shot. | Surface Casin Oil String AMOUNT OF MUD USED |

XOBO OF DRULL-STEM AND SPECIAL TE

If drill-stem or other special tests or deviation surveys were made, submit report on separate sheet and attach herete

TOOLS USED

| Rotary tool | ls were us | ed from | 0 | feet to | 4939 | feet, | and from | ••••• | feet | t to | feet. |
|-------------|------------|----------------------|---|-------------|---------------------------------------|---|-----------|---------------------|-------------|---------------------------|---------------|
| Cable tools | were use | d from | | feet to | | fee t, | and from | | fee | t to | fee t. |
| | | | | | PROI | DUCTION | | | | | |
| Put to Pro | ducing | | August] | | 19 58 | **** | | | | | |
| | _ | | n during the fir | | | _ | har | male of lie | uid of whic | .h <u>ա</u> | |
| OIL WEL | | | | | | | | | | | |
| | | • | | | | | % water | ; and | <u>V</u> | % was sedin | nent. A.P.I. |
| | Grav | /i ty | 33 | ••••• | | | | | ٠ | | |
| GAS WEL | L: The | production | during the fire | st 24 hou | rs was | | M.C.F. pl | us | | •••• | barrels of |
| | liqui | d Hydroca | rbon. Shut in I | ressurc | 1 | bs. | | | | | |
| | - | • | | | | | | | | | |
| - | | | | | | | | | | | |
| PLEA | SE INDI | ICATE BI | | | | ONFORMA | NCE WITI | H GEOGE | | SECTION OF | |
| | 3.5 | 20 | Southeastern | | | | | • | | estern New Me | |
| | | | | | Devonian | | • | | - | ruitland | |
| | | | | | Montoya | | | | | | |
| | | | | | Simpson | | | | | | |
| T. 7 Rive | ers | | | Т. | McKee | | | | '. Menefee | | |
| T. Queen | 16 | 313 | | т. | Ellenburger | ••••• | | т. | Point Look | out | |
| T. Grayb | urg | | | т. | Gr. Wash | ••••• | | т. | Mancos | | |
| | | | | | Granite | | | | | • | |
| | | | *************************************** | | •••••• | | | _ | | | |
| | | | | | | - | | | | | |
| | | | | | •••••••••• | | | | | ************************* | |
| | | | | | | | •••• | Т. | | | **** |
| T. Miss | ••••• | | | Т. | •• | ····· | ····· | т. | | | •••••• |
| | | | | | FORMAT | ION REC | ORD | | | | |
| From | То | Thickness in Feet | | Formatio | on. | From | То | Thicknes in Feet | s | Formation | |
| 0 | 55 | 55 | Cap Rock | | | | | | | | |
| 55 | 1750 | 1695 | Red beds | | | | | | | | |
| 1750 | 3710 | | | | e and red | | | | | | |
| 3410 | 4613 | 1203 | with dole | | e and anh; streaks. | yarı ce | | | | | |
| 4613 | 14939 | 326 | | | sand stre | elc | | | | | |
| | | | - | | | - | | | | . • | |
| | | | | | *** | | | | | | |
| | | | | | | | | | | | |
| 1 | | | | | | American Company Compa | | | | | |
| Ì | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | The state of the s | | | | | |
| | | | | | | | | | | | |
| i | | | | | | | 1 | | | | |
| ļ | | | ! | • | | | | | | | |
| | | | | | | | a cag | | | | |
| | | I | | | · · · · · · · · · · · · · · · · · · · | ! | <u></u> | | <u> </u> | | <u></u> |

ATTACH SEPARATE SHEET IF ADDITIONAL SPACE IS NEEDED

| I hereby swear or affirm that the information given herewith is a | complete and correct record of the well as | nd all work done on it so far |
|---|--|-------------------------------|
| as can be determined from available records. | Parcy C. Guinn Address Box 4395, Midland, | August h. 1958 |
| Company or Operator. Cabot Carbon Company | Address Box 4395, Midland, | (Date) Texas |
| Name Percy C. O'Quinn | Position or Title Dist. Prod. | Supt. |