Submit 3 Copies to Appropriate	Fnemy	State of Net Minerals and Natur	w Mexico ral Resources Department	Form C-103
District Office	Likigy,		a Resources Department	Revised 1-1-89
P.O		P.O. Bo		WELL API NO. 30-025-03238
DISTRICT II P.O. Drawer DD, Artesia, NM	1 88210 S	anta Fe, New Me	xico 87504-2088	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			STATE FEE X	
Tool No Diatos Ru., MACC, P	10 0/410			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name
1. Type of Well:	GAS			
2. Name of Operator	WELL	OTHER I	njection Well	East Pearl Queen Unit
Pyramid Energ	y, Inc.			8. Well No. #24
3. Address of Operator				9. Pool name or Wildcat
4. Well Location	ro. Suite /00	) San Antonio	o, Texas 78232	Pearl Queen
Unit LetterH	_: <u>1980</u> Feet Fr	rom The North	Line and	660 Feet From The <u>East</u> Line
2.2				
Section 28	Towns		Range 35E	NMPM Lea County
		3736 DF	ether DF, RKB, RT, GR, etc.)	
11.	Check Appropri		ate Mature - CNL (* D	
	Check Appropri		ate Nature of Notice, R	Report, or Other Data
NOTICE	OF INTENTIO	N 10:	SUF	
		r	—, I	
ERFORM REMEDIAL WOR		N TO: 3 AND ABANDON [		BSEQUENT REPORT OF:
ERFORM REMEDIAL WOR EMPORARILY ABANDON		r	—, I	
ERFORM REMEDIAL WOR EMPORARILY ABANDON		GAND ABANDON		G OPNS.
NOTICE PERFORM REMEDIAL WOR EMPORARILY ABANDON PULL OR ALTER CASING DTHER:		GAND ABANDON	REMEDIAL WORK     COMMENCE DRILLING     CASING TEST AND CI	ALTERING CASING
PERFORM REMEDIAL WOR EMPORARILY ABANDON PULL OR ALTER CASING DTHER:	COF INTENTION	G AND ABANDON [ NGE PLANS [	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CO OTHER: Return we	G OPNS.
PERFORM REMEDIAL WOR EMPORARILY ABANDON PULL OR ALTER CASING DTHER:	E OF INTENTION	G AND ABANDON [ NGE PLANS [ y state all pertinent detail	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CI OTHER: Return we	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection wing estimated date of starting any proposed
ERFORM REMEDIAL WOR EMPORARILY ABANDON FULL OR ALTER CASING OTHER:	E OF INTENTION	G AND ABANDON [ NGE PLANS [ y state all pertinent detains g. RIH w/4-3	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CO OTHER: Return we ils, and give pertinent dates, inclu	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection whing estimated date of starting any proposed Comment @ 45311 Drilled comment
PERFORM REMEDIAL WOR TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Comp work) SEE RULE 1103. 12/1/90 MIF to to 01/2/91 Dri	CHAN CHAN	G AND ABANDON [ NGE PLANS [ y state all periment details g. RIH w/4-3 ed cement ret n "AG" Packer	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CO OTHER: Return we ils, and give pertinent dates, inclu 3/4" bit. Tagged of cainer 4591'-4593'.	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection x wding estimated date of starting any proposed cement @ 4531'. Drilled cement Drilled cement 4593' 4750'
PERFORM REMEDIAL WOR EMPORARILY ABANDON PULL OR ALTER CASING DTHER:	CHAN CHAN	G AND ABANDON [ NGE PLANS [ y state all periment detains g. RIH w/4-3 ed cement ret n "AG" Packer & drilled sc	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CO OTHER: Return we ils, and give pertinent dates, inclu 3/4" bit. Tagged of cainer 4591'-4593'. © 4750'-4753'. I cale to 4920'.	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection wding estimated date of starting any proposed cement @ 4531'. Drilled cement . Drilled cement 4593'-4750'. Drilled cement to 4798' & broke
PERFORM REMEDIAL WOR EMPORARILY ABANDON PULL OR ALTER CASING DTHER:	CHAN CHAN	G AND ABANDON [ NGE PLANS [ y state all periment detains g. RIH w/4-3 ed cement ret n "AG" Packer & drilled sc erforate Uppe	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CO OTHER: Return we ils, and give perimeni dates, inclue 3/4" bit. Tagged of cainer 4591'-4593'. © 4750'-4753'. I cale to 4920'. Proven 4698'-4707	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection wding estimated date of starting any proposed cement @ 4531'. Drilled cement . Drilled cement 4593'-4750'. Drilled cement to 4798' & broke 7' (4 shots/foot)
PERFORM REMEDIAL WOR TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Comp work) SEE RULE 1103. 12/1/90 MIF to to 01/2/91 Dri thr 01/3/91 POC 01/4/91 Ram	CHAN CHAN	G AND ABANDON [ NGE PLANS [ y state all periment detains g. RIH w/4-3 ed cement ret n "AG" Packer & drilled sc erforate Uppe Packer, seat	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CO OTHER: Return we dis, and give periment dates, inclue alignment 4591'-4593'. 4750'-4753'. ale to 4920'. cale to 4920'. cale to 4920'. cale to 4920'. cale to 4920'. cale to 4920'.	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection wding estimated date of starting any proposed cement @ 4531'. Drilled cement . Drilled cement 4593'-4750'. Drilled cement to 4798' & broke 7' (4 shots/foot). its. of 2-3/8" 4.7# Jaff FUT
PERFORM REMEDIAL WOR TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Comp work) SEE RULE 1103. 12/1/90 MIF to to 01/2/91 Dri thr 01/3/91 POC 01/4/91 Ram to pla 01/6/91 bac	CHAN CHAN	GAND ABANDON [ NGE PLANS [ y state all perinent detains g. RIH w/4-3 ed cement ret n "AG" Packer & drilled sc erforate Uppe Packer, seat bg. Set Pack e test and pl	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CI OTHER: Return we ils, and give pertinent dates, inclu data iner 4591'-4593'. 4750'-4753'. I cale to 4920'. cale to 4920'.	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection wding estimated date of starting any proposed cement @ 4531'. Drilled cement . Drilled cement 4593'-4750'. Drilled cement to 4798' & broke
PERFORM REMEDIAL WOR TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Comp work) SEE RULE 1103. 12/1/90 MIF to to 01/2/91 Dri thr 01/3/91 POC 01/4/91 Ram to pla 01/6/91 bac	CHAN CHAN	GAND ABANDON [ NGE PLANS [ y state all perinent detains g. RIH w/4-3 ed cement ret n "AG" Packer & drilled sc erforate Uppe Packer, seat bg. Set Pack e test and pl	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CI OTHER: Return we ils, and give pertinent dates, inclu data iner 4591'-4593'. 4750'-4753'. I cale to 4920'. cale to 4920'.	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection x whing estimated date of starting any proposed cement @ 4531'. Drilled cement . Drilled cement 4593'-4750'. Drilled cement to 4798' & broke 7' (4 shots/foot). jts. of 2-3/8" 4.7# J-55 EUE well up for injection Date
PERFORM REMEDIAL WOR TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Comp work) SEE RULE 1103. 12/1/90 MIF to to 01/2/91 Dri thr 01/3/91 POC 01/4/91 Ram to pla 01/6/91 bac	CHAN CHAN	GAND ABANDON [ NGE PLANS [ y state all perinent detains g. RIH w/4-3 ed cement ret n "AG" Packer & drilled sc erforate Uppe Packer, seat bg. Set Pack e test and pl	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CI OTHER: Return we ils, and give pertinent dates, inclu data iner 4591'-4593'. 4750'-4753'. I cale to 4920'. cale to 4920'.	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection x whing estimated date of starting any proposed cement @ 4531'. Drilled cement . Drilled cement 4593'-4750'. Drilled cement to 4798' & broke 7' (4 shots/foot). jts. of 2-3/8" 4.7# J-55 EUE well up for injection Date
PERFORM REMEDIAL WOR TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Comp work) SEE RULE 1103. 12/1/90 MIF to to 01/2/91 Dri thr 01/3/91 POC 01/4/91 Ram to pla 01/6/91 bac	CHAN CHAN	GAND ABANDON [ NGE PLANS [ y state all perinent detains g. RIH w/4-3 ed cement ret n "AG" Packer & drilled sc erforate Uppe Packer, seat bg. Set Pack e test and pl	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CI OTHER: Return we ils, and give pertinent dates, inclu data iner 4591'-4593'. 4750'-4753'. I cale to 4920'. cale to 4920'.	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection x whing estimated date of starting any proposed cement @ 4531'. Drilled cement . Drilled cement 4593'-4750'. Drilled cement to 4798' & broke 7' (4 shots/foot). jts. of 2-3/8" 4.7# J-55 EUE well up for injection Date
PERFORM REMEDIAL WOR TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Comp work) SEE RULE 1103. 12/1/90 MIF to to 01/2/91 Dri thr 01/3/91 POC 01/4/91 Ram to pla 01/6/91 bac	CHAN CHAN	GAND ABANDON [ NGE PLANS [ y state all perinent detains g. RIH w/4-3 ed cement ret n "AG" Packer & drilled sc erforate Uppe Packer, seat bg. Set Pack e test and pl	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CI OTHER: Return we ils, and give pertinent dates, inclu data iner 4591'-4593'. 4750'-4753'. I cale to 4920'. cale to 4920'.	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection wding estimated date of starting any proposed cement @ 4531'. Drilled cement . Drilled cement 4593'-4750'. Drilled cement to 4798' & broke 7' (4 shots/foot). jts. of 2-3/8" 4.7# J-55 EUE well up for injection
PERFORM REMEDIAL WOR TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Comp work) SEE RULE 1103. 12/1/90 MIF to to 01/2/91 Dri thr 01/3/91 POC 01/4/91 Ram to pla 01/6/91 bac 200	CHAN CHAN	GAND ABANDON [ NGE PLANS [ y state all perinent details g. RIH w/4-3 ed cement ret n "AG" Packer & drilled sc erforate Uppe Packer, seat bg. Set Pack e test and pl psi.	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CO OTHER: Return we dis, and give pertinent dates, inclue all of the second dates, inclue all the second dates and the cainer 4591'-4593'. Cainer 4591'-4593'. Cainer 4591'-4593'. Cainer 4591'-4593'. Cainer 4698'-4707 Caing nipple & 163 Car @ 4654'. Hook Caced well on active	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection x whing estimated date of starting any proposed cement @ 4531'. Drilled cement . Drilled cement 4593'-4750'. Drilled cement to 4798' & broke 7' (4 shots/foot). jts. of 2-3/8" 4.7# J-55 EUE well up for injection Date
PERFORM REMEDIAL WOR EMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Comp work) SEE RULE 1103. 12/1/90 MIF to to 01/2/91 Dri thr 01/3/91 POC 01/4/91 Ram to pla 01/6/91 bac 200	CHAN CHAN	G AND ABANDON [ NGE PLANS [ y state all periment details g. RIH w/4-3 ed cement ret n "AG" Packer & drilled sc erforate Uppe Packer, seat bg. Set Pack e test and pl psi.	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CO OTHER: Return we ils, and give pertinent dates, inclu 3/4" bit. Tagged of cainer 4591'-4593'. C 4750'-4753'. If cale to 4920'. C Queen 4698'-4707 C QUEEN 4654'. HOOK	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection ding estimated date of starting any proposed cement @ 4531'. Drilled cement . Drilled cement 4593'-4750'. Drilled cement to 4798' & broke 7' (4 shots/foot). jts. of 2-3/8" 4.7# J-55 EUE well up for injection. Ran ye injection w/approximately
PERFORM REMEDIAL WOR EMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Comp work) SEE RULE 1103. 12/1/90 MIF to to 01/2/91 Dri thr 01/3/91 POC 01/4/91 Ran to pla 01/6/91 bac 200 I hereby certify that the information SKONATURET	CHAN CHAN	GAND ABANDON [ NGE PLANS [ y state all perinent details g. RIH w/4-3 ed cement ret n "AG" Packer & drilled sc erforate Uppe Packer, seat bg. Set Pack e test and pl psi.	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CO OTHER: Return we ils, and give perimeni dates, inclue along 4591'-4593'. Cainer 4591'-4593'. Cainer 4591'-4593'. Cainer 45920'. Cainer 4698'-4707 Caing nipple & 163 Care @ 4654'. Hook Caced well on active	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection wding estimated date of starting any proposed cement @ 4531'. Drilled cement . Drilled cement 4593'-4750'. Drilled cement to 4798' & broke 7' (4 shots/foot). jts. of 2-3/8" 4.7# J-55 EUE well up for injection. Ran ve injection w/approximately hgineer 02/05/91
ERFORM REMEDIAL WOR EMPORARILY ABANDON ULL OR ALTER CASING THER:	CHAN CHAN	G AND ABANDON [ NGE PLANS [ y state all periment detail g. RIH w/4-3 ed cement ret n "AG" Packer & drilled sc erforate Uppe Packer, seat bg. Set Pack e test and pl psi.	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CO OTHER: Return we ils, and give pertinent dates, inclu 3/4" bit. Tagged of cainer 4591'-4593'. C 4750'-4753'. If cale to 4920'. C Queen 4698'-4707 C QUEEN 4654'. HOOK	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection wding estimated date of starting any proposed cement @ 4531'. Drilled cement . Drilled cement 4593'-4750'. Drilled cement to 4798' & broke 7' (4 shots/foot). jts. of 2-3/8" 4.7# J-55 EUE well up for injection. Ran ve injection w/approximately hgineer 02/05/91
PERFORM REMEDIAL WOR EMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Comp work) SEE RULE 1103. 12/1/90 MIF to to to 01/2/91 Dri thr 01/3/91 POC 01/4/91 Ram to pla 01/6/91 bac 200 I hereby certify that the information SKONATURE	CHAN CHAN	S AND ABANDON [ NGE PLANS [ y state all periment detail g. RIH w/4-3 ed cement ret n "AG" Packer & drilled sc erforate Uppe Packer, seat bg. Set Pack e test and pl psi.	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CO OTHER: Return we ils, and give pertinent dates, inclu 3/4" bit. Tagged of cainer 4591'-4593'. C 4750'-4753'. If cale to 4920'. C Queen 4698'-4707 C QUEEN 4654'. HOOK	ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB ell to active injection ding estimated date of starting any proposed cement @ 4531'. Drilled cement . Drilled cement 4593'-4750'. Drilled cement to 4798' & broke 7' (4 shots/foot). jts. of 2-3/8" 4.7# J-55 EUE well up for injection. Ran ye injection w/approximately