

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>E-584</b>
7. Unit Agreement Name <b>West Pearl Queen Unit</b>
8. Farm or Lease Name
9. Well No. <b>102</b>
10. Field and Pool, or Wildcat <b>Pearl Queen</b>
12. County <b>Lea</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Water Injection Well</b>
2. Name of Operator <b>Gulf Oil Corporation</b>
3. Address of Operator <b>Box 670, Hobbs, New Mexico 88240</b>
4. Location of Well UNIT LETTER <b>D</b> <b>990</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>29</b> TOWNSHIP <b>19-S</b> RANGE <b>35-E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>3778' GL</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4791' PB.

Pulled both strings of tubing and Guiberson RCL-2 dual packer. Set CI BP at 4830' and dumped 4 sacks of cement on top of BP. (39'). (Guiberson Type A packer left in hole at 4907'). Installed casing swage and 2" valve. To be carried as temporarily abandoned.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>H. J. Braggeale</i></u>	TITLE <u>Area Engineer</u>	DATE <u>November 5, 1973</u>
APPROVED BY <u><i>[Signature]</i></u>	TITLE <u></u>	DATE <u></u>

CONDITIONS OF APPROVAL, IF ANY: