

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
**E-1922**

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL  GAS WELL  OTHER

2. Name of Operator  
**Gulf Oil Corporation**

3. Address of Operator  
**P. O. Box 670, Hobbs, NM 88240**

4. Location of Well  
UNIT LETTER **L** **2310** FEET FROM THE **South** LINE AND **330** FEET FROM  
THE **West** LINE, SECTION **32** TOWNSHIP **19S** RANGE **35E** NMPM.

7. Unit Agreement Name  
**West Pearl Queen Unit**

8. Farm or Lease Name

9. Well No.  
**158**

10. Field and Pool, or Wildcat  
**Pearl Queen**

15. Elevation (Show whether DF, RT, CR, etc.)  
**3720' GL**

12. County  
**Lea**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Circulate abandonment mud. Test casing 500#. Spot plug 4150'-4050'. Perf 1975' with (4) 1/2" JH with 90° phasing. Pump into perf. Set cement retainer at 1922'. Pump 350 sacks Class "H" cement with 16% gel and 100 sacks Class "C". Run temperature survey, TSTOC 100'. Set 50' plug at surface per Tony Platsmire with OCD. Set dry hole marker. Clear and clean location. P&A complete 1-27-81.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *R.D. Pitre* TITLE Area Engineer DATE 2-16-81

APPROVED BY *W.D. Plattmire* TITLE Oil & Gas Inspector DATE

CONDITIONS OF APPROVAL, IF ANY: