

NO. OF COPIES RECEIVED	
DISTRIBUTION	
ANTA FE	
FILE	
J.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No. <u>E-5886</u>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

☒ LL ☐ SAB WELL ☐ OTHER- 1. Name of Operator <u>Chevron U.S.A. Inc.</u> 2. Address of Operator <u>P. O. Box 670, Hobbs, NM 88240</u> 3. Location of Well 4. Well Letter <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>19S</u> RANGE <u>35E</u> NMPM. 5. Elevation (Show whether DF, RT, GR, etc.) 6. County <u>Lea</u>	7. Unit Agreement Name <u>West Pearl Queen Unit</u> 8. Farm or Lease Name <u>West Pearl Queen Unit</u> 9. Well No. <u>149</u> 10. Field and Pool, or Wildcat <u>Pearl Queen</u>
--	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
☐ REMEDIAL WORK ☐ PARTIALLY ABANDON ☐ ALTER CASING ☐ CR	☐ PLUG AND ABANDON ☐ CHANGE PLANS ☐	☐ REMEDIAL WORK ☐ COMMENCE DRILLING, OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER <u>Ind</u>	☐ ALTERING CASING ☐ PLUG AND ABANDONMENT ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Temporarily Abandoned - CIBP Act @ 4740'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

<u>[Signature]</u>	TITLE <u>New Mexico Area Supt.</u>	DATE <u>2-24-87</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		
DATE <u>4-1-88</u>	TITLE _____	DATE _____

OTHER APPROVALS, IF ANY:

TA Expires 3-1-88