

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-101
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR APPLICATIONS TO DRILL OR TO REOPEN OR REEQUIP A WELL TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - FORM C-101, FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐																
1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER- Water Injection Well		5. State Oil & Gas Lease No. B-5887																
2. Name of Operator Gulf Oil Corporation		7. Unit Agreement Name																
3. Address of Operator P. O. Box 670, Hobbs, NM 88240		8. Farm or Lease Name West Pearl Queen Unit																
4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 33 TOWNSHIP 19-S RANGE 35-E N.M.P.M.		9. Well No. 161																
15. Elevation (Show whether DF, RT, GR, etc.) 3681' GL		10. Field and Pool, or Wildcat Pearl Queen																
12. County Lea																		
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data <table border="0"> <tr> <td colspan="2">NOTICE OF INTENTION TO:</td> <td colspan="2">SUBSEQUENT REPORT OF:</td> </tr> <tr> <td>PERFORM REMEDIAL WORK ☐</td> <td>PLUG AND ABANDON ☐</td> <td>REMEDIAL WORK ☐</td> <td>ALTERING CASING ☐</td> </tr> <tr> <td>TEMPORARILY ABANDON ☐</td> <td>CHANGE PLANS ☐</td> <td>COMMENCE DRILLING OPS. ☐</td> <td>PLUG AND ABANDONMENT ☒</td> </tr> <tr> <td>PULL OR ALTER CASING ☐</td> <td>OTHER ☐</td> <td>CASING TEST AND CEMENT JOBS ☐</td> <td></td> </tr> </table>			NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐	TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☒	PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:																
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐															
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☒															
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐																
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.																		

5015' TD. 5005' PB.

Pulled producing equipment. Set a CIBP at 4677'. Spotted 15 sacks (210') Class C cement from 4677' to 4467'. Load hole w/ abandonment fluid. Set a 4 1/2" cement retainer at 1702'. Cement through retainer with 350 sacks Class C cement w/ 5# salt, 2% CaCl2. Cap retainer with 125' cement. Spot a 50' cement plug to surface. Set a dry hole marker. P & A Complete.

18. I, Thereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>W. B. Sikes Jr</u>	TITLE <u>Area Engineer</u>	DATE <u>3-3-78</u>
APPROVED BY <u>G. A. J. [Signature]</u>	TITLE <u>INSPECTOR</u>	DATE <u>3-3-78</u>

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 6 1978

CH. CONSERVATION COMM.
HOBBS, N. M.