

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease

State ☒ Fed ☐

5. State Oil & Gas Lease No.

E-5841

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- Water Injection Well

7. Unit Agreement Name

W. Pearl Queen Unit

8. Form of Lease Name

2. Name of Operator

Gulf Oil Corporation

9. Well No.

146

3. Address of Operator

P. O. Box 670, Hobbs, NM 88240

10. Field and Pool, or Wildcat

Pearl Queen

4. Location of well

UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM

THE West LINE, SECTION 33 TOWNSHIP 19S RANGE 35E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

3702' GL

12. County

Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
FULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER TA ☒

ALTERING CASING
PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any pro work) SEE RULE 1105.

POH with tubing. Set CIBP at 4700'; water started flowing. Found CIBP at 3198' with junk basket. Came up hole to 1859'. Drill 6" CIBP, fill 1859' to bottom. Set CIBP at 4664'. Circulate hole with packer fluid. TA complete 6-3-81

Orig. Signed by
Jerry Sexton
Dist. L. Supv.

Expires 6/9/82

JUN 9 1981

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: R.D. Pitzer

TITLE: Area Engineer

DATE: 6-8-81