

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Box DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-8072
7. Lease Name or Unit Agreement Name Lea 688 State
8. Well No. 1
9. Pool name or Wildcat Eumont Yates 7 Rivers

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator JFG Enterprise
3. Address of Operator P.O. Box 100, Artesia, New Mexico 88211-0100	4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>East</u> Line and <u>660</u> Feet From The <u>North</u> Line Section <u>25</u> Township <u>20S</u> Range <u>35E</u> NMPM <u>Lea</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) DF 3658	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

January 9, 1989:

Plugged and abandoned:

Set 100' cement plug at perms 3994'-4024' and tagged cement.

Loaded hole with 10# Salt Gel.

Cut 4½" casing at 1307'. Spotted 50' in and out. Tagged it.

Set cement plug 50' in and out of 10 3/4" casing. Tagged cement.

Set 10 sack surface plug at top hole and installed dry hole marker.

Restored surface as set out in regulations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. T. Jackson TITLE Co-Owner DATE 09/17/89

TYPE OR PRINT NAME J.T. Jackson TELEPHONE NO. (505) 746-9680

(This space for State Use)

**OIL & GAS INSPECTOR**

**MAY 29 1990**

APPROVED BY [Signature] TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: