

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Encl. Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-039883
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1040
7. Lease Name or Unit Agreement Name State YA
8. Well No. 1
9. Pool name or Wildcat Eumont Yates SR QN

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Mack Energy Corporation	
3. Address of Operator P.O. Box 1359 Artesia, New Mexico 88211-1359	
4. Well Location Unit Letter P : 990 Feet From The South Line and 990 Feet From The East Line Section 1 Township 19-S Range 36-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set 5 1/2 CIBP at 3850' Cap W/35' cement
- 2) Load Hole W/mud
- 3) Cut and pull 5 1/2 casing from approx 2700'
- 4) Spot 100' cement plug at 5 1/2 stub 50' in 50' out tag
- 5) Spot 100' cement plug at 8 5/8 shoe 50' in 50' out tag 8 5/8 shoe at 325'
- 6) Spot 10 sacks of cement plug at surface set P.A. marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maldonado

TITLE Superior

DATE 8-12-94

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNATURE OF JERRY SEXTON  
DISTRICT SUPERVISOR

TITLE \_\_\_\_\_ DATE \_\_\_\_\_

AUG 12 1994