

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-04003
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1327
7. Lease Name or Unit Agreement Name	Monstate
8. Well No.	5
9. Pool name or Wildcat	Eumont Yates 7 Rivers Queen
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3723' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Texaco Producing Inc.
3. Address of Operator P.O. Box 730, Hobbs, NM 88240	4. Well Location Unit Letter H : 1650 Feet From The North Line and 990 Feet From The East Line Section 13 Township 19S Range 36E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3723' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU. Killed well. Pld tbg.
- 2) TIH w/bit & bailer. C/O to 3725'.
- 3) Ran 5-1/2" pkr & set @ 3511'. Tstd csg to 1000#. OK.
- 4) A/OH 3570-3725' w/3000 gals 15% NEFE acid. Max P-1800#. AIR 2 BPM.
- 5) F/OH w/46,000 gals gelled wtr & CO₂ & 120,000# 12/20 sd. Max P-5000#. AIR 30 BPM.
- 6) Pld pkr. C/O sd to 3725'.
- 7) Ran tbg, rods, pmp. SN @ 3570'.
- 8) OPT 06-05-90, 0 BO, 0 BW, 421 MCFD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. D. Ridenour TITLE Engineer's Assistant DATE 06-15-90
TYPE OR PRINT NAME L. D. Ridenour TELEPHONE NO. 393-7191

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUN 18 1990

00000000

JUN 18 1990

CO
HOBBS OFFICE