

Engineer District 1

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEQUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Notice by Checking	g Below	
rice of Intention Change Plans	Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper	×
rice of Intention Plug Well	Notice of Intention to Plug Back	Notice of Intention to Set Liner	
rice of Intention Squeeze	Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)	
rice of Intention Gun Perforate	Notice of Intention (Other) Fracture treat	Notice of Intention (Other)	-
. CONSERVATION COMMISSIO	Hobbs, New Mexico	Asgust 27,	19 56
tlemen:			
	to do certain work as described below at the	• .8	
ulf Oil Corporation	Lea State "DA"	Well No3in	/Init)
SE 1/4 NW 1/4 of Sec. 1	4 , T 19-S , R 36-E ,NM	IPM Funons	(OMC)
	FULL DETAILS OF PROPOSED PLAN		
(FOL	FULL DETAILS OF PROPOSED PLAN LOW INSTRUCTIONS IN THE RULES AN	ND REGULATIONS)	
(FOL	FULL DETAILS OF PROPOSED PLAN	ND REGULATIONS)	at as fol
(FOLI	FULL DETAILS OF PROPOSED PLAN LOW INSTRUCTIONS IN THE RULES AN auction it is proposed to drill and tubing.	ND REGULATIONS) desper and fracture trea	•
order to increase prod 1. Pull rods, pump 2. Run 2-7/8" tubi	FULL DETAILS OF PROPOSED PLAN LOW INSTRUCTIONS IN THE RULES AN AUCTION it is proposed to drill	ND REGULATIONS) desper and fracture trea	•
(FOLI order to increase prod 1. Pull rods, pump 2. Run 2-7/8" tubi caliper. 3. Pull 2-7/8" tub	FULL DETAILS OF PROPOSED PLAN LOW INSTRUCTIONS IN THE RULES AN auction it is proposed to drill and tubing. Ing with 6-1/8" bit and drill fi ing and bit. Bun 2-7/8" tubing	ND REGULATIONS) deeper and fracture tree row 4050-41301. Run sho	rt arm
order to increase prod 1. Pull rods, pump 2. Run 2-7/8" tubi caliper. 3. Pull 2-7/8" tub formation pasket	FULL DETAILS OF PROPOSED PLAN LOW INSTRUCTIONS IN THE RULES AN auction it is proposed to drill and tubing. Ing with 6-1/8" bit and drill fi ing and bit. Bun 2-7/8" tubing r at approximately 4050".	nd REGULATIONS) deeper and fracture tree rom 4050-4130 . Run shor g with Lynes self anchor:	rt arm
order to increase prod 1. Pull rods, pump 2. Run 2-7/8" tubi caliper. 3. Pull 2-7/8" tub formation packet 4. Treat formation sand per gallon	FULL DETAILS OF PROPOSED PLAN LOW INSTRUCTIONS IN THE RULES AN action it is proposed to drill and tubing. Ing with 6-1/8" bit and drill fi ing and bit. Bun 2-7/8" tubing r at approximately 4050'. below packer with 10,000 galler	ND REGULATIONS) deeper and fracture tree rom 4050-4130. Run short g with Lynes self anchor: ons gelled lease oil with	rt arm ing
(FOLI order to increase prod 1. Pull rods, pump 2. Run 2-7/8" tubicaliper. 3. Pull 2-7/8" tub formation packet 4. Treat formation sand per gallon	FULL DETAILS OF PROPOSED PLAN LOW INSTRUCTIONS IN THE RULES AN action it is proposed to drill and tubing. Ing with 6-1/8" bit and drill fi ing and bit. Bun 2-7/8" tubing r at approximately 4050'. below packer with 10,000 galled ing and packer. Run 2-3/8" tul	ND REGULATIONS) deeper and fracture tree rom 4050-4130. Run short g with Lynes self anchor: ons gelled lease oil with	rt arm ing
(FOLIO corder to increase product of the increase product of the increase product of the increase product of the increase of t	FULL DETAILS OF PROPOSED PLAN LOW INSTRUCTIONS IN THE RULES AN action it is proposed to drill and tubing. Ing with 6-1/8" bit and drill fi ing and bit. Bun 2-7/8" tubing r at approximately 4050'. below packer with 10,000 galled ing and packer. Run 2-3/8" tul	ND REGULATIONS) deeper and fracture tree rom 4050-4130. Run short g with Lynes self anchor: ons gelled lease oil with	rt arm ing
order to increase prod 1. Pull rods, pump 2. Run 2-7/8" tubicaliper. 3. Pull 2-7/8" tub formation packet 4. Treat formation sand per gallon 5. Pull 2-7/8" tub well to product:	FULL DETAILS OF PROPOSED PLAN LOW INSTRUCTIONS IN THE RULES AN auction it is proposed to drill and tubing. Ing with 6-1/8" bit and drill fr ing and bit. Bun 2-7/8" tubing r at approximately 4050". below packer with 10,000 galls ing and packer. Run 2-3/8" tulion.	ND REGULATIONS) deeper and fracture tree rom 4050-4130. Run short g with Lynes self anchor: ons gelled lease oil with	rt arm ing
order to increase prod 1. Pull rods, pump 2. Run 2-7/8" tubi caliper. 3. Pull 2-7/8" tub formation packet 4. Treat formation sand per gallon 5. Pull 2-7/8" tub well to product	FULL DETAILS OF PROPOSED PLAN LOW INSTRUCTIONS IN THE RULES AN auction it is proposed to drill and tubing. Ing with 6-1/8" bit and drill fr ing and bit. Bun 2-7/8" tubing r at approximately 4050". below packer with 10,000 gallating and packer. Run 2-3/8" tul- ing and packer. Run 2-3/8" tul-	deeper and fracture treatment to the from 4050-4130. Run shows with Lynes self anchor: one gelled lease oil with hing, rods and pump and the fine of the fracture treatment.	rt arm ing
order to increase prod 1. Pull rods, pump 2. Run 2-7/8" tubi caliper. 3. Pull 2-7/8" tub formation packet 4. Treat formation sand per gallon 5. Pull 2-7/8" tub well to product AUG 28 10 proved	FULL DETAILS OF PROPOSED PLAN LOW INSTRUCTIONS IN THE RULES AN auction it is proposed to drill and tubing. Ing with 6-1/8" bit and drill fr ing and bit. Bun 2-7/8" tubing r at approximately 4050". below packer with 10,000 gallating and packer. Run 2-3/8" tul- ing and packer. Run 2-3/8" tul-	ND REGULATIONS) deeper and fracture tree rom 4050-4130. Run short g with Lynes self anchor: ons gelled lease oil with	rt arm ing
order to increase prod 1. Pull rods, pump 2. Run 2-7/8" tubicaliper. 3. Pull 2-7/8" tub formation packet 4. Treat formation sand per gallon 5. Pull 2-7/8" tubiwell to product:	FULL DETAILS OF PROPOSED PLAN LOW INSTRUCTIONS IN THE RULES AN action it is proposed to drill and tubing. Ing with 6-1/8" bit and drill from any with 6-1/8" bit and drill from at approximately 4050. below packer with 10,000 gallering and packer. Run 2-3/8" tulion. By	deeper and fracture treatment to the row 4050-4130. Run shows with Lynes self anchor: one gelled lease oil with hing, rods and pump and the row of the row	rt arm ing

Address.

Box 2167, Hobbs, New Mexico