

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL	<b>X</b>	NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICO

Hobbs, New Mexico  
(Place)

June 6, 1955  
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Shell Oil Company State MA Well No. 1 in sp#  
(Company or Operator)  
SE 1/4 SE 1/4 of Sec. 21, T 19-S, R. 36-E, NMPM., Monument Area Wildeat Pool  
(40-acre Subdivision)  
Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK  
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

VERBAL APPROVAL WAS RECEIVED TO PLUG & ABANDON STATE MA-1 PER TELEPHONE CONVERSATION BETWEEN MR. PORTER OF THE OIL CONSERVATION COMMISSION AND MR. D. de VRIES OF SHELL OIL COMPANY ON JUNE 3, 1955

We propose to plug and abandon as following:

- (1) Displace the hole with mud laden fluid
- (2) Pull open ended tubing up to 3900' and spot 10 sack neat cement from 3900' to 3820' into 5-1/2" casing. Pull tubing.
- (3) Determine freeze point of 5-1/2" casing by stretch test. Shoot off and pull 5-1/2" casing.
- (4) Spot 25 sack cement thru open ended tubing above 5-1/2" casing remaining in hole, but not deeper than 1500' to isolate hole above 900' from salt section (top of salt 1750
- (5) Pull tubing to 320' and spot 15 sack plug in bottom of 8-5/8" casing. Spot 10 sack cement plug at surface. Erect 4" x 4' marker as required by Rule 202.

Approved....., 19.....  
Except as follows:

Approved  
OIL CONSERVATION COMMISSION

By.....  
Title.....

Shell Oil Company  
Company or Operator  
By D. C. Meyers Original signed by D. C. Meyers  
Position Division Mechanical Engineer  
Send Communications regarding well to:  
Name Shell Oil Company  
Address Box 1957, Hobbs, New Mexico