

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-04032
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Northwest Eumont Unit
8. Well No. #134
9. Pool name or Wildcat Eumont Yates

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well Gas Well Other

2. Name of Operator **Rhombus Operating Co., Ltd.**

3. Address of Operator
P.O. Box 8316, Midland, Texas 79708-8316

4. Well Location
 Unit Letter **N** : **330** feet from the **South** line and **2,323** feet from the **West** line
 Section **22** Township **19-S** Range **36-E** NMPM County **Lea**

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3,644' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK PLUG AND ABANDON
- TEMPORARILY ABANDON CHANGE PLANS
- PULL OR ALTER CASING MULTIPLE COMPLETION
- OTHER:

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ALTERING CASING
- COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
- CASING TEST AND CEMENT JOB
- OTHER:

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.


08/05/02 Notified OCD, Sylvia Dickey. MIRU Triple N #25 and plugging equipment. POOH w/ rods. ND wellhead, NU BOP. POOH w/ tbg. RIH w/ gauge ring on wireline to 1,725', unable to get down. RIH w/ tbg to 4,015'. Loaded hole w/ mud and pumped 25 sx C cmt @ 4,185'. POOH w/ 20 stands and SDFN.

08/06/02 E.L. Gonzales w/ OCD on location. RIH and tagged cmt @ 3,665'. Circulated hole w/ mud and POOH w/ tbg to 2,803'. Pumped 25 sx C cmt 2,803 - 2,389'. POOH w/ tbg. Cut casing @ 1,612'. POOH w/ 4 1/2" casing, tally 1,616.55'. RIH w/ tbg 1,647' and pumped 50 sx C cmt @ 1,647'. POOH w/ tbg and WOC 2 hrs. RIH and tagged cmt @ 1,565'. Pumped 35 sx C cmt 1,565 - 1,426'. POOH w/ tbg and SDFN.


08/07/02 RIH and tagged cmt @ 1,440'. Pumped 30 sx C cmt 400 - 284'. ND BOP and pumped 50 sx C cmt 60' to surface. POOH w/ tbg, RDMO to #165.

08/09/02 Cut off wellhead and capped well, installed marker. Backfilled pit and cellar, cut off anchors.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE **Engineer** DATE **08/28/02**
 Type or print name **James F. Newman, P.E.** Triple N Services, Inc. Telephone No. **915-687-1994**

(This space for State use)

APPROVED BY 
 Conditions of approval, if any:
OC FIELD REPRESENTATIVE II/STAFF MANAGER
GW

Approved as to plugging of the Well Bore. TITLE **JAN 30 2003**
 Liability under bond is retained until surface restoration is completed.