

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - FORM C-101 FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER ☐

1. Name of Operator
Texaco Inc.

2. Address of Operator
P. O. Box 728, Hobbs, New Mexico 88240

3. Location of Well
UNIT LETTER **N** **1980** FEET FROM THE **West** LINE AND **660** FEET FROM
THE **South** LINE, SECTION **23** TOWNSHIP **19-S** RANGE **36-E** N.M.P.M.

5a. Indicate Type of Lease
State **2** Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name
W. M. Weir

9. Well No.
2

10. Field and Pool, or Wildcat
Eumont Queen Gas

12. County
Lea

11. Elevation (Show whether DF, RT, GR, etc.)
3712' (DF)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
WELL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
		OTHER ☐ Eliminate pressure on csg. strings at the surface	

7. Describe (in) set or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pull tubing & pkr. Kill well.
2. Set RBP @ 3695'. Test 7" csg. w/600 # ; tested OK.
3. Spot 2 sx. sand on RBP @ 3695'. Log well.
4. Set RBP @ 2800' Spot 2 sx. sand on RBP. Perf. 7" csg. w/2-JS @ 1575'.
5. Set Cement retainer @ 1535'. Cement 9 5/8" csg. annulus w/300 sx. class 'C' cement. Ran temperature survey and top of cement @ 1468'.
6. Perf. 7" csg. w/2-JS @ 1300'. Squeeze perf. w/300 sx. class 'C' cement. DOC & retainer. Test csg. w/650# for 30 minutes, 3:15-3:45 PM, 2-2-79. Tested OK.
7. Install producing equipment. Test & return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *W. L. Cooper* TITLE Asst. Dist. Supt. DATE 2-16-79

APPROVED BY *John Runyan* TITLE Geologist DATE FEB 18 1979

CONDITIONS OF APPROVAL, IF ANY: