

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
3002504050

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-1961

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
New Mexico "J" State

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

8. Well No.
1

2. Name of Operator
Texaco Producing Inc.

9. Pool name or Wildcat
Eunice Monument GBSA

3. Address of Operator
P.O. Box 730, Hobbs, NM 88240

4. Well Location
Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line
Section 24 Township 19S Range 36E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3722' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU. Pld rods & tbgs. Cleaned out fill to 4046'.
- 2) Ran GR-CNL-CLL from 4022-3150'.
- 3) Perf'd OH 3743-47,63,72,83,90,3805,10,25,38,41-45,56-59,68,74-78,83,97,3908,21,24-30,41,66-69,81,83,92,4000,4018'. (Total holes - 100)
- 4) TIH w/pkr set @ 3700'. Ld backside. Tested to 500#. OK.
- 5) Acidized w/5000 gals 15% NEFE. Max P-2100#. AIR 8 BPM.
- 6) Pld pkr out of hole. Ran prod equip.
- 7) OPT 05-25-90, 5 BOPD, 8 BWPD, 88 MCFPD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. D. Ridenour TITLE Engineer's Assistant DATE 05-30-90

TYPE OR PRINT NAME L. D. Ridenour TELEPHONE NO. 393-7191

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE JUN 04 1990

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 01 1990

ODD
HOBBS OFFICE