

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
UNIT A FE	
ILE	
S.G.S.	
AND OFFICE	
PERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-1961
7. Unit Agreement Name -
8. Farm or Lease Name New Mexico 'J' State
9. Well No. 2
10. Field and Pool, or Wildcat Eunice Monument Grayburg San Andres
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT L-1 (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
Name of Operator TEXACO Inc.
Address of Operator P. O. Box 728 - Hobbs, New Mexico 88240
Location of Well UNIT LETTER <u>N</u> <u>1980</u> FEET FROM THE <u>West</u> LINE AND <u>660</u> FEET FROM THE <u>South</u> LINE, SECTION <u>24</u> TOWNSHIP <u>19-S</u> RANGE <u>36-E</u> NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

3715' (DF)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

RM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
RARELY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
IN ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	
OR <u>Addl. Perfs in Grayburg-San Andres</u> <input checked="" type="checkbox"/>			

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed operations) SEE RULE 1103.

Rig up. Pull rods and tubing. Install BOP.
Clean out well to 4021' (TD).
Log well.
Perforate selected intervals.
Acidize open hole interval w/4500 gals 15% NE acid in 3-stages w/300# rock salt between stages.
Install pumping equipment. Test and place on production.

I certify that the information above is true and complete to the best of my knowledge and belief.

[Signature] TITLE Asst. District Supt. DATE 5-16-77

Orig. Signed by
Jerry Sexton
Dist 1, Supv.

TITLE _____ DATE _____

IS OF APPROVAL, IF ANY:

RECEIVED

MAY 17 1977

COMM. DIV.
U.S. DEPT. OF JUSTICE