

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-04105
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Northwest Eumont Unit
8. Well No. #153
9. Pool name or Wildcat Eumont Yates
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,657' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other ☐ Injection ☒

2. Name of Operator **Rhombus Operating Co., Ltd.**

3. Address of Operator
P.O. Box 8316, Midland, Texas 79708-8316

4. Well Location

Unit Letter **A** **660** feet from the **North** line and **660** feet from the **East** line

Section **34** Township **19-S** Range **36-E** NMPM County **Lea**

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3,657' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

08/12/02 Notified OCD, Buddy Hill. Dug and lined pit. MIRU Triple N #25 and plugging equipment. ND wellhead, NU BOP. POOH w/ tbg. RIH w/ workstring to 3,712'. Loaded hole w/ mud and pumped 25 sx C cmt @ 3,712'. WOC and tagged cmt @ 3,568'. RIH w/ tbg to 2,800' and pumped 25 sx C cmt 2,800 - 2,652'. POOH w/ tbg and SDFN.

08/13/02 RIH w/ wireline and cut casing @ 1,302', POOH w/ wireline. RU casing tools and POOH w/ 7" casing, tally 1,313.75'. RIH w/ tbg and pumped 50 sx C cmt @ 1,350'. POOH w/ tubing and SDFN.

08/14/02 Tagged cmt @ 1,205'. Pumped 25 sx C cmt 1,205 - 1,129'. POOH w/ tbg to 409' and pumped 65 sx C cmt @ 409'. POOH w/ tubing and WOC. RIH and tagged cmt @ 228'. Pumped 20 sx C cmt 60' to surface. RDMO.

08/16/02 Cut off wellhead and capped well, installed marker. Backfilled pit and cellar, cut off anchors.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE **Engineer** DATE **08/28/02**

Type or print name **James F. Newman, P.E.** Triple N Services, Inc. Telephone No. **915-687-1994**
(This space for State use)

APPROVED BY  TITLE **COMPLIANCE OFFICER** DATE **OCT 05 2002**

Conditions of approval, if any:

GWW