

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name Northwest Eumont Unit
2. Name of Operator Gulf Oil Corporation		8. Farm or Lease Name
3. Address of Operator Box 670, Hobbs, New Mexico 88240		9. Well No. 154
4. Location of Well UNIT LETTER G , 1980 FEET FROM THE North LINE AND 2310 FEET FROM THE East LINE, SECTION 34 , TOWNSHIP 19-S , RANGE 36-E N.M.P.M.		10. Field and Pool, or Wildcat Eumont
15. Elevation (Show whether DF, RT, GR, etc.) 3643' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Convert well to water injection,	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3950' TD.

Pull producing equipment and clean out, if necessary. Run 2-3/8" tubing coated internally and tension type packer. Set packer at approximately 3800'. Start injecting water. After well pressures up will load tubing - casing annulus with treated water.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY
C. D. BORLAND

SIGNED **C. D. BORLAND** TITLE **Area Production Manager** DATE **January 22, 1971**

APPROVED BY **[Signature]** TITLE **SUPERVISOR DISTRICT** DATE **JAN 26 1971**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 25 1971

**OIL CONSERVATION COMM.
HOBBS, N. M.**