

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-025-04110</b>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <b>Rhombus Operating Co., Ltd.</b>		6. State Oil & Gas Lease No.
3. Address of Operator <b>P.O. Box 8316, Midland, Texas 79708-8316</b>		7. Lease Name or Unit Agreement Name: <b>Northwest Eumont Unit</b>
4. Well Location Unit Letter <b>E</b> : <b>1,980</b> feet from the <b>North</b> line and <b>990</b> feet from the <b>West</b> line Section <b>34</b> Township <b>19-S</b> Range <b>36-E</b> NMPM County <b>Lea</b>		8. Well No. <b>#165</b>
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat <b>Eumont Yates</b>

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

08/07/02 Notified OCD, Sylvia Dickey. MIRU Triple N #25 and plugging equipment. ND wellhead, NU BOP. RIH w/ tbg and tagged CIBP @ 3,700'. RU cementer and circulated hole w/ mud, pumped 25 sx C cmt 3,700 - 3,453'. POOH w/ tubing to 2,822' and circulated mud, pumped 25 sx C cmt 2,822 - 2,575'. POOH w/ tbg. RIH w/ wireline and perforated @ 1,400'. POOH w/ wireline. RIH w/ packer to 1,003'. Loaded hole, set packer, pressured up to 1,500 psi, no rate. POOH w/ packer. RIH w/ tbg to 1,451'. Loaded hole and pumped 25 sx C cmt 1,451 - 1,204'. POOH w/ tbg and WOC 2 hrs. RIH and tagged cmt @ 1,205'. Perforated casing @ 400'. RIH w/ packer to 30'. Loaded hole, set packer, established circulation and squeezed 55 sx C cmt 400 - 168'. SDFN.

08/08/02 Tagged cmt @ 235'. ND BOP and RIH w/ tbg to 235' and circulated 25 sx C cmt 235' to surface. POOH w/ tbg, RDMO to #166.

08/09/02 Cut off wellhead and capped well, covered pit and cellar, removed anchors.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James F. Newman TITLE Engineer

Type or print name James F. Newman, P.E. Triple N Services, Inc.

Telephone No. 915-687-1994

(This space for State use)

APPROVED BY Johnny Robinson TITLE COMPLIANCE OFFICER

Conditions of approval, if any:

