

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-04140
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-154-3
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 19
8. Well No.	5
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTION	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P.O. DRAWER D, MONUMENT, NM 88265	
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>1</u> Township <u>20S</u> Range <u>36E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: CONVERT TO INJECTION WELL. ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1905 (12-30-96 THRU 01-06-97)

TYLER WELL SVC. & STAR TOOL MIRU. SCREWED INTO & UNSEATED SV. TOH W/SUCKER RODS, K-BARS AND PLUNGER. ND WELLHEAD, RELEASED TAC, & NU BOP. TOH W/TUBING & PUMP BBL. TIH W/RBP, SN & 119 JTS. TBG. SET & GOT OFF RBP @ 3,706'. LOADED & CIRC. LINER CSG. CLEAN W/FW. PRESS. TST'D. CSG. TO 560# & CHARTED 30 MIN. TST. CSG. HELD. RELEASED RBP. TOH W/19 JTS. TBG. RBP FREE @ 3,115'. TOH W/100 JTS. TBG., SN & MODEL "G" RBP. TIH W/BIT, BIT SUB, & 126 JTS. TBG. TAGGED PBTD @ 3,901'. TOH W/126 JTS. TBG., SUB & BIT. SCHLUMBERGER MIRU. PERF'D. 4-1/2" LINER FR. 3,705'-3,727' (45 HOLES) 2 SPF, 80 DEG. PHASED, USING 3-3/8" HEGS CHGS. SCHLUMBERGER RDMO. TIH W/FTI'S SONIC HAMMER, SN, & 108 JTS. TBG. TOOL @ 3,356'. TIH W/17 jts. tbg. acidizing TOOL @ 3,788'. INSTALLED STRIPPER HEAD. KNOX SVCS. MIRU. PREWASHD 4-1/2" LINER PERFS. FROM (CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 01-07-97
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use) ORIGINAL FILED IN THE STATE OF NEW MEXICO

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JAN 17 1997

JCBN

da