

Amerada Petroleum Corporation,  
Robbs, New Mexico.

November 21, 1938.

Mr. F.J. Vesely, State Oil and Gas Inspector,  
Box 522, Carlsbad, New Mexico.

Dear Mr. Vesely:

Through error, we cemented 15" OD. casing in our State-H, well #1  
Mountain Area, at 145° or 15° in the Red Bed, instead of cementing it at 250° or deeper  
as required by the State Oil Conservation Commission. As correction to this error, we  
will use enough cement behind the intermediate string, of 9 5/8" casing, to bring the  
cement to the bottom of the cellar.

Yours very truly,

Amerada Petroleum Corporation.

Sign J.A. Strick

ICR

卷之三十一

卷之三十一

卷之三

Digitized by srujanika@gmail.com

www.bart.com • 800-661-8686

Digitized by srujanika@gmail.com

147. The Board of Directors of the Company has adopted the following Code of Ethics:

requested to "check and to addendum to Newland, your new bid at 70% to 75% for 2012 construction  
in some areas of Holt which are included under the original bid date and by beginning on  
any portion of September 1st, 2012. Addendum will be limited to those areas over 1000  
sq. ft. and to be modified and or revised

卷之三

www.ijerph.org | ISSN: 1660-4601 | DOI: 10.3390/ijerph17030823

A horizontal line with a series of small, irregular marks or dashes along its length, possibly representing a scale or a specific measurement.