		· · · · · · · · · · · · · · · · · · ·
NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICA ONB GONSERVE DOG BOMMISSION	C-102 and C-103 Effective 1-1-65
FILE		
U.S.G.S.	May 13 9 14 M '68	5a. Indicate Type of Lease
	MAY 13 3 14 MI OU	State Fee
OPERATOR		5. State Oil & Gas Lease No.
	J	B-1386
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
		7. Unit Agreement Name
WELL WELL	OTHER-	
2. Name of Operator		8. Farm or Lease Name
Amerada Petroleum Corporation		State "H"
3. Address of Operator		9. Well No.
P. O. Box 668 - Høbbs, New Mexico		3
4. Location of Well		10. Field and Poel, or Wildcat
UNIT LETTER J	2173 FEET FROM THE South LINE AND 1787 FEET FR	Momment Blinebry
	ON 1 TOWNSHIP 20-S BANGE 36-E	
	on 1 TOWNSHIP 20-S RANGE 36-B NM	
	on <u>1</u> TOWNSHIP <u>20-8</u> RANGE <u>36-B</u> NMI 15. Elevation (Show whether DF, RT, GR, etc.)	
THE <b>East</b> LINE, SECTION	15. Elevation (Show whether DF, RT, GR, etc.) 3575' DF	DM. 12. County Lea
THE <b>East</b> LINE, SECTION	15. Elevation (Show whether DF, RT, GR, etc.) <b>3575' DF</b> Appropriate Box To Indicate Nature of Notice, Report or (	Бм. 12. County Lea Other Data
THE <b>Bast</b> LINE, SECTION	15. Elevation (Show whether DF, RT, GR, etc.) <b>3575' DF</b> Appropriate Box To Indicate Nature of Notice, Report or (	DM. 12. County Lea
THE <b>East</b> LINE, SECTION	15. Elevation (Show whether DF, RT, GR, etc.) <b>3575' DF</b> Appropriate Box To Indicate Nature of Notice, Report or (	Бм. 12. County Lea Other Data
THE Bast LINE, SECTION	15. Elevation (Show whether DF, RT, GR, etc.) <b>3575' DF</b> Appropriate Box To Indicate Nature of Notice, Report or O NTENTION TO: SUBSEQUE	DM. 12. County Lea Other Data NT REPORT OF: ALTERING CASING
THE Bast LINE, SECTION 16. Check A NOTICE OF IN PERFORM REMEDIAL WORK	15. Elevation (Show whether DF, RT, GR, etc.) <b>3575' DF</b> Appropriate Box To Indicate Nature of Notice, Report or O NTENTION TO: PLUG AND ABANDON REMEDIAL WORK	Dither Data NT REPORT OF:
THE LINE, SECTION 16. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	15. Elevation (Show whether DF, RT, GR, etc.) <b>3575' DF</b> Appropriate Box To Indicate Nature of Notice, Report or C NTENTION TO: PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB	DM. 12. County Lea Dther Data NT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
THE LINE, SECTION 16. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	15. Elevation (Show whether DF, RT, GR, etc.) <b>3575' DF</b> Appropriate Box To Indicate Nature of Notice, Report or ONTENTION TO: PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	Dem. 12. County Lea Dther Data NT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT

Pulled production equipment. Cleaned out with sand pump. Ran tubing and packer. Acidized perfs. 5676' to 5717' and open hole 5717' to 5727' with 7000 gals. 15% Unisol acid with 1800# rock salt for diverter. Pulled tubing and packer. Reran production equipment and resumed pumping. No change in producing status.

DATE 5-8-68 District Superintendent YE SIGNED TITLE APPROVED B DATE CONDITION APPROV

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.