

Submit 3 Copies to Appropriate

Energy, Minerals and Natural Resources Department

Form C.103

Revised 1-1-89

to Appropriate District Office	Energy, witherars and waterar				
DISTRICT J P.O. Box 1980, Hobbs NM 88241-1980 OIL CONSERVATION DIVISION 2040 Pacheco St.			WELL API NO. 30-025-04158		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, N		5. Indicate Type of	Lease STATE	FEE 🗆
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. B-1656-2		
SUNDRY NOTICES AND REPORTS ON WELLS					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name North Monument G/SA Unit Blk. 18		
1. Type of Well: OIL GAS WELL WELL	OTHER In	jection Well			
2. Name of Operator			8. Well No.		
Amerada Hess Corporation			9. Pool name or Wildcat		
3. Address of Operator P. O. Box 840, Semin	Eunice Monument G/SA				
4 Well Location			180	. The Sout	th _{Line}
Unit Letter K : 19	Peet From The West	Line and19	Feet From	. The	Line
Section 2	Township 20S	Range 36E	NMPM	Lea	County
Section 2	10. Elevation (Show wh	ether DF, RKB, RT, GR, et	c.)		
	<u>/////////////////////////////////////</u>	C DT - 42	Donort or O	ther Date	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF:					
NOTICE OF	INTENTION TO:	Sui	BSEQUEN I	REPORT	Ji .
	PLUG AND ABANDON] REMEDIAL WORK	X	ALTERING CASI	NG L
PERFORM REMEDIAL WORK		COMMENCE DRILLING	G OPNS	PLUG AND ABAN	NDONMENT [
TEMPORARILY ABANDON	CHANGE PLANS —				
PULL OR ALTER CASING	_	CASING TEST AND C	EMENI JOB —		_
OTHER:		OTHER:			
	Operations (Clearly state all pertinent	details, and give pertinent d	ates, including estima	ated date of startin	ig any proposed
2-24 thru 3-5-99					
w/5-3/4" bit to 3980' Hole. Attempted to construct the Svc., TIH w/cement ref WOC. TIH w/5-3/4" bit Circ. clean & press to & sand to 3980'. RU E charge. Cleaned out to	Removed wellhead, installe & TOH. American Fracmaste irc. sand. TIH w/bit & dri tainer set at 3712' & pumpe t & tagged at 3712'. Drld ested csg. to 500 PSI. He Baker Atlas & string shot (fill to TD at 3983' circ. of set pkr. at 3719' Circ.	er spotted 75 sks. S ld. hard sand to 380 ed 150 sks. Class "C . retainer & cement ld OK. Drld. out ce O.H. fr. 3910' - 394 clean. TIH w/6-5/8"	8'. RU B.J. " cement. to 3806'. ment to 3808' 0' w/1000 gr.		
and the second s	is true and complete to the best of my know	vledge and belief.			
SIGNATURE Not 4		_{тпье} Bus. Svc. Spec	c. II	DATE	3-9-99
TYPE OR PRINT NAME ROY L. Whe	eler, Jr.			TELEPHONE NO. 9	<u>15 758-6778</u>
(This space for State Use)	50 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				

Removed BOP & installed wellhead. Press. tester 6-5/8" csg. to 560 PSI for 30 min. Held OK. Chart attached. RDPU, cleaned location, & continued injecting water.

the contract of the contract o