

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Continental Oil Company		8. FARM OR LEASE NAME Reed Sanderson Unit	
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, New Mexico 88240		9. WELL NO. 3	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FWL, Section 3, T-20S, R-36E Lea County, New Mexico.		10. FIELD AND POOL, OR WILDCAT Mamont Pool	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3597 D.F.	
11. SEC. T. R. M. OR BLK. AND SURVEY OR AREA 20S, 36E		12. COUNTY OR PARISH Lea	
13. STATE N.M.			

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(Other) Convert to Injection ☒ (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In connection with the Reed Sanderson Unit Waterflood, it is proposed to convert the subject well to water injection by the following procedure:

1. Run tubing and bit and cleanout to 4450'
2. Perforate 5 1/2" casing from 3914' to 3916'
3. Treat perfs w/ 500 gallons LSINE acid
4. Run cement-lined tubing w/packer set at approximately 3700'.
5. Connect well up and commence water injection through the tubing.

NMCCC Order R-1131 was issued on September 11, 1968, authorizing institution of the Reed Sanderson Unit Waterflood.

A subsequent report will be submitted upon completion of this work.

18. I hereby certify that the foregoing is true and correct

SIGNED James W. Hark

TITLE Geological Engineer

DATE 10/1/68

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

USGS-5 ATL-Ros-2 CEN-Mid-2 PAN AM-Hor-4-2