

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR
(Other instructions
reverse side)

DATE
ON

LEASE DESIGNATION AND SERIAL NO.
LC-031622B
IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER Injection
2. NAME OF OPERATOR Conoco Inc.
3. ADDRESS OF OPERATOR P.O. Box 760 - Hobbs, NM 88240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
660/N+E Unit A
14. PERMIT NO. 30-025-04190 15. ELEVATIONS (Show whether OF, RT, GR, etc.)

7. UNIT AGREEMENT NAME
Rod Sanderson Unit
8. FARM OR LEASE NAME
9. WELL NO.
1
10. FIELD AND POOL, OR WILDCAT
Summit Unit 7 Rwy. Queen
11. SEC., T., R., OR BLK. AND SURVEYOR AREA
4-20S-36E
12. COUNTY OR PARISH
Lea 13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) <u>Plug & Abandon</u>	(Other) ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

4/30/90 MIRR, installed BOP. Pulled tubing. Pumped 5 BFW, 25 SX Class "C" cmt, 5 BFW and displace w/8.3 BML brine. Bot. plug from 3698-3451' KB. POOH & lay down. 16 jts. tbg. Pump & circ. 5 1/2" w/706HL MLF. P.U. to 439'. Pumped 48 A/s. Class "C" cmt to surface. Had good returns. Filled top of 5 1/2" w/cmt. install P&A marker. Restore location. See attached wellbore schematic.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

H.A. Sugar

TITLE

Conservation Coordinator

DATE

5/22/90

(This space for Federal or State office use)

APPROVED BY

FOR RECORD

CONDITIONS OF APPROVAL, IF ANY:

ONLY

DATE

MAY 31 1990

(6) BLM (3) OGD

*See Instructions on Reverse Side (1) File

Reed-Sanderson Unit No. 1

660' ENL & 660' FEL

Section 4, T-20S, R-36E

Hea Cỏ, NM

PEA (5/89)

Well head cut @
celler base &
back filled w/ sand
4" P/A marker welded
on B5/P C.S.g.

TOC @ Surface

4.8 Sx Class "C" cement

3 5/8", 24 x 24, 5-55 casing
set @ 322' (TOC @ 308.00')

BOC @ 439

$\tau_{oc} \approx 3451'$

25 Sx of Class "C" cement

Baker Model D-1 ZAA
cement retainer @ 3700'

Perfs: Eumont Yates - IR Queen

3894'-3910'

3932'-58'

4001' - 08'

4020' - 50'

5 1/2", 14 gpf, H-40 casing set
@ 4099' (TOC @ 50'-face).

FBTD @ 40251

TO £ 4100'

W. P. Marshall
5/2/90

TR
4/28/89